

8.	(CONFIRMED I	ſ
	٠	NORTH PIEF	<

SEALER.





LEGEND:

NEW CONCRETE





NOTES: 1. CONFIRMED REPAIR LOCATIONS: TWO BEARINGS AT WEST END OF SOUTH ABUTMENT



SECTION: TYPICAL NORTH PIER COLUMN DELAMINATION REPAIR SCALE: 1:5

NOTES: 1. SAWCUT PERIPHERY OF REPAIR AREA TO 25 DEEP. 2. DRILL HOLES AND INSTALL THREADED RODS. 4. SANDBLAST ALL EXPOSED REINFORCING STEEL. TIE REINFORCING MESH TO THREADED RODS.

A

7. PLACE NEW CONCRETE TO COMPLETE PATCH REPAIR. REPAIR LOCATIONS:

ER COLUMNS 12 AND 14

9. NARROW CRACKS TO BE REPAIRED WITH SILANE

	LOCATION APPROVED	BM ELEV								PROFESSIONAL'S SEAL
	SUPR. U/G STRUCTURES DATE COMMITTEE						MORRIS	10RRISON HERSHFIELD		A.D.G.
MANITOBA Certificate of Authorization	NOTE: LOCATION OF UNDERGROUND STRUCTURES					DESIGNED BY	AG	CHECKED BY	BAP	RE GILARSK Member 32144
No. 1736	AS SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE BUT NO GUARANTEE IS GIVEN THAT ALL EXISTING UTILITIES ARE SHOWN OR THAT THE GIVEN LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION.	D	ISSUED FOR TENDER	18/09/04	BAP	DRAWN BY	AH	APPROVED BY	BE	
METRIC WHOLE NUMBERS INDICATE MILLIMETRES DECIMALIZED NUMBERS INDICATE METRES		C B	ISSUED FOR 95% DESIGN REVIEW ISSUED FOR 50% DESIGN REVIEW REV 1	18/08/07 18/06/28 18/04/03	BAP AG	HOR SCALE AS SHOWN VERT SCALE AS SHOWN	RELEASED FOR CONS		CONSULTANT FILE N	
		No.	REVISIONS	YY/MM/DD	BY	DATE		DATE		W160034 - DD S

REPAIR INSTRUCTIONS:

2. REMOVE DETERIORATED GROUT. 3. PLACE NEW GROUT TO APPROXIMATE LIMITS OF EXISTING GROUT PAD.

1. INSTALL STEEL BLOCKING TO SUPPORT DIAPHRAGM.

