



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

<b>BUILDING NAME:</b> ELMWOOD KILDONAN POOL	<b>INSPECTION DATE:</b> April 1/2005
<b>BUILDING CODE:</b> PI-03	<b>INSPECTED BY:</b> Karl Bauch & Jayson Cyncora
<b>BUILDING ADDRESS:</b> 909 CONCORDIA AVE.	Year Built: 1975

**LEGEND-** Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster  
**TI**-Tank Insulation **C**-Ceiling **F**-Flooring **DW**-Ductwork  
Condition: **G**-Good **NR**-Need Repair  
Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
<b>MEZZ. FLOOR LEVEL</b>							
East Mechanical Room	Pipe Elbows	PW		R	2Y		no
<b>BASEMENT LEVEL</b>							
Kitchen / Staff Room	Pipe Elbows	PW		G	2 Y		no
Men's Locker Room	Pipe Elbows above Toilet	PW		G	2 Y		no
Janitors Room	Pipe Elbows	PW		G	2 Y		no
Corridor @ Entrance to Women's Locker Room	Pipe Elbows	PW		G	2 Y		no
Corridor @ Entrance to Boiler Room	Pipe Elbows	PW		G	2 Y		no
Boiler Room	Pipe Elbows	PW		G	2 Y		no
	Tank Insulation	TI		G	2 Y		no
Tunnel / North Side	Pipe Elbows	PW		R	2 Y		no
Tunnel / South Side	Pipe Elbows	PW		R	2 Y		no
Tunnel / Fan Area	Pipe Elbows	PW		G	2 Y		no
Spare Parts Room	Pipe Elbows	PW		G	2 Y		no
Engineers Office	Pipe Elbows	PW		G	2 Y		no
Exterior Block Walls	Walls appear to be empty. <b>(Do not contain Vermiculite insulation.)</b>						