



**ASBESTOS INVENTORY CONTROL**

BUILDING SERVICES DIVISION

<b>BUILDING NAME:</b> Isaac Brock CC	<b>INSPECTION DATE:</b> February 27, 2006
<b>BUILDING CODE:</b> CC-039	<b>INSPECTED BY:</b> Karl Bauch & Jayson Cyncora
<b>BUILDING ADDRESS:</b> 715 Telfer	Construction Date: 1960

Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster  
**TI**-Tank Insulation **C**-Ceiling **F**-Flooring **D**- Ducting  
**LEGEND-** Condition: **G**-Good **NR**-Need Repair  
 Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
Basement activity room	Floor tiles may contain asbestos	F		G	2Y		no
Main floor hallway	Floor tiles may contain asbestos	F		G	2Y		no
Main activity room	Floor tiles may contain asbestos (Floor covered with underlay and new sheet flooring in 2003)	F		G	2Y		no
Furnace room	Plaster on ceiling may contain asbestos <b>(Visual examination of a sample shows no evidence of asbestos fibres)</b>	PL		G	2Y		no