



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: SARGENT PARK POOL	INSPECTION DATE: March 31/2005
BUILDING CODE: PI-09	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 999 SARGENT AVE.	Year Built: 1976

LEGEND- Application Type: PW-Pipe Wrap SO-Spray On HB-Hardboard EN-Encapsulated R-Removed PL-Plaster
 TI-Tank Insulation C-Ceiling F-Flooring DW-Ductwork
 Condition: G-Good NR-Need Repair
 Inspection Frequency: B-Per 6 Months Y-Yearly 2Y-Two Years 5Y-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
MEZZ. FLOOR LEVEL							
North Air handling Room	Spray on ceiling and ductwork (Duct Insulation is Fibreglass)	SO DW	0 %	G G	2 Y	yes	no
North Mezz. Lobby & offices	Ceiling tile	C	0 %	G	2 Y	yes	
North Mezz. Above ceiling tile	Pipe elbows and roof drains	PW		G	2 Y		no
South Mezz. Above ceiling tile	Pipe elbows and roof drains	PW		G	2 Y		no
South Mezz. Air handling room	Pipe elbows	PW		G	2 Y		no
North pool deck ceiling	Roof drains	PW		G	2 Y		no
South pool deck ceiling	Roof drains	PW		G	2 Y		no
MAIN FLOOR LEVEL							
East Side Gym Ceiling	Ceiling Tile	C		G	2 Y		no
Activity Room # 4	Scratch Coat	C	5%	G	2 Y	yes	
North hallway to Activity Rms	Scratch Coat	C	0%	G	2 Y	yes	
BASEMENT LEVEL							
Hot Water Storage Tank Room	Pipe Elbows Tank Insulation East tank insul tested – 0% asbestos	PW TI	0%	NR G	2 Y 2 Y	yes	
Garage Mezzanine	Pipe Elbows	PW		G	2 Y		no
Corridor along track to Garage	Pipe Elbows	PW		G	2 Y		no
North Track	Pipe Elbows	PW		G	2 Y		no
South Track	Pipe Elbows	PW		G	2 Y		no
Filtration and Pump room/pit	Pipe elbows	PW		G	2 Y		no
West crawlspace	Pipe elbows	PW		G	2 Y		no
Electrical Tool Storage Room	Pipe elbows	PW		G	2 Y		no
Electrical Chemical Storage room	Pipe elbows	PW		G	2 Y		no
Electrical Room	Pipe elbows Duct insulation	PW D		G G	2 Y 2 Y		no no
Pool Engineers Office	Pipe elbows	PW		G	2 Y		no