



PHOTOGRAPH 9: FACING SOUTH - AT STATION 1+80



PHOTOGRAPH 10: FACING SOUTH - AT STATION 1+85




PHOTOGRAPH 11: FACING SOUTH - AT STATION 1+95, PRIMARY FAILURE ZONE ON LEFT




PHOTOGRAPH 12: FACING SOUTH - AT STATION 1+95, PRIMARY FAILURE ZONE, AREA OF GABION BASKET RETAINING WALL AND RIP-RAP PROTECTION BLANKET



PHOTOGRAPH 13: FACING NORTH - AT STATION 1+95, PRIMARY FAILURE ZONE, AREA OF GABION BASKET RETAINING WALL AND RIP-RAP PROTECTION BLANKET



PHOTOGRAPH 14: FACING SOUTH - AT STATION 2+25 AREA WITH NO RETAINING WALL



PHOTOGRAPH 15: FACING SOUTH - AT STATION 2+35, AREA WITH NO RETAINING WALL



PHOTOGRAPH 16: FACING SOUTH - AT STATION 2+47, END OF WALKWAY



#6 - 854 Marion Street  
Winnipeg, MB R2J 0K4  
Phone: (204) 233-1694  
Fax: (204) 235-1579

ENG. STAMP:



**APEGM**  
Certificate of Authorization  
ENG-TECH Consulting Limited  
No.2475 Expiry: April 30, 2009

CLIENT:  
**CITY OF WINNIPEG**

PROJECT:  
**SEINE RIVER WALKWAY  
RE-CONSTRUCTION AT DESAUTELS  
STREET, WINNIPEG, MANITOBA**

DWG DESCRIPTION:  
**PHOTOGRAPHS 9-16**

SCALE:

DRAWN BY: **NAM** DATE: **MAY 2008**

FILE No.: **07-217-03** CLIENT DWG/FIG. No.:

ENG-TECH DWG/FIG. No.:  
**3 OF 7**

REV.:  
**0**