

APPENDIX C

SITE PHOTOGRAPHS



Mile 50.31 Lower Box Benching



Mile 50.31 Lower Construction Joint



Mile 50.31 North Side Lower Box



Mile 50.31 South Headwall



Mile 53.75 Drainage Siphon Lower Box at S. End Looking N. (Note: Good condition)



Mile 53.75 Drainage Siphon S. Side Looking N. at S. Headwall



Mile 53.75 Drainage Siphon S. Side Looking Down S. Throat (Note 2 Transverse Cracks)



Mile 53.75 Drainage Siphon N. Side Looking S. at N. Headwall