



## ASBESTOS INVENTORY CONTROL

<b>Building Name:</b>	City Hall Administration Building
<b>Building Code:</b>	CB-01
<b>Building Address:</b>	510 Main
<b>Inspection Date:</b>	January 28, 2010
<b>Inspected By:</b>	Karl Bauch & Vic Mendoza
<b>Construction Date:</b>	1964

<b>Legend</b>	Application Type: <b>AF</b> - Fabric <b>C</b> - Ceiling Tile <b>D</b> - Ducting <b>F</b> - Flooring <b>HB</b> - Hardboard <b>PE</b> - Pipe Elbow Insulation <b>PI</b> - Pipe Insulation <b>PL</b> - Plaster <b>SO</b> - Spray On <b>TI</b> - Tank Insulation <b>TP</b> Transite Pipe <b>V</b> - Vermiculite Condition: <b>G</b> - Good <b>NR</b> - Needs Repair <b>R</b> - Removed
---------------	---

Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
<b>For Floors with textured ceilings &amp; asbestos covered beams refer to asbestos drawings.</b>						
<b>Sub - Basement</b>						
Main Open Areas	Pipe Insulation (Hard Insulation)	PI		G	Yes	
	Pipe Elbow Insulation	PE		G		No
	Tank Insulation	TI		G		No
West Crawlspace	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D		G		No
East Crawlspace	Pipe Elbow Insulation	PE	80%	G	Yes	
	Duct Insulation	DI	80%	G	Yes	
Tunnel to Council Building	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
Under Stairs from Lobby	9 x 9 Floor Tile	F		G		No
<b>Basement</b>						
Garage Area	Pipe Insulation - Yellow sample #2 & north wall	PI	0	G	Yes	
	Pipe Elbow Insulation - Beige Sample #1	PE	25-85	G	Yes	
	Pipe Elbow Insulation - Gray sample #3	PE	0	G	Yes	
	Pipe Elbow Insulation - Sample #4 small pipe	PE	30-80	G	Yes	
Big Storage Room East Side of Garage	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	9 x 9 Floor Tile	F		G		No
R10 - North Pipe Chase in Storage Room	Pipe Elbow Insulation	PE		G		No
Fenced Storage	Duct Insulation	D	0		Yes	
R2 - East Pipe Chase in Storage Room	Pipe Elbow Insulation	PE		G		No
Small Storage Room East Side of Garage	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	9 x 9 Floor Tile	F		G		No
R3 - East Stairwell	9 x 9 Floor Tile	F		G		No
R4 - Pipe Chase in East Stairwell	Pipe Elbow Insulation	PE		G		No

Application Type: AF- Fabric C - Ceiling Tile D - Ducting F - Flooring HB - Hardboard PE - Pipe Elbow Insulation PI - Pipe Insulation PL - Plaster SO - Spray On <b>Legend</b> TI - Tank Insulation TP Transite Pipe V - Vermiculite Condition: G - Good NR - Needs Repair R - Removed						
Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
East Women's Washroom	Ceiling and Wall Plaster	PL		G		No
East Men's Washroom	Ceiling Plaster	PL		G		No
West Men's Washroom	Ceiling Plaster	PL		G		No
East Stairwell	Ceiling and Wall Plaster	PL	0		Yes	
Staff Lunchroom	Pipe Elbow Insulation Above Ceiling	PE		G		No
	12 x 12 Floor Tile	F	3%	G	Yes	
East Staff Locker Room	12 X 12 Floor Tile	F	3%	G	Yes	
R5 - Staff Lunchroom -West	12 x 12 Floor Tile	F		G		No
Locker Room Pipe Chase	Pipe Elbow Insulation in Pipe Chase	PE		G		No
East Crawlspace	Pipe Elbow Insulation	PE		G		No
Southwest Crawlspace	Pipe Elbow Insulation	PE	10%	G	Yes	
Tunnel to Council Building	Textured Ceiling	PL		G		No
Tunnel to Parkade	Pipe Elbow Insulation above Ceiling Space	PE	5-10%	G	Yes	
	Wall Scratch coat	PL	0%		Yes	
Central Control Hallway & Side Rooms	Pipe Elbow Insulation (Above Grid)	PE		G		No
	9 x 9 Floor Tile	F		G		No
R1 - Pipe Chase East Side of Central Control Office	Pipe Elbow Insulation Sample #5 small pipe	PE	30	G	Yes	
	Pipe Elbow Insulation Sample #6 big pipe	PE	30	G	Yes	
Central Control Office	Pipe Elbow Insulation (Above Grid)	PE		G		No
	Possible 9 x 9 Floor Tile Under Carpet	F		G		No
Café Prep/Storage Rm	Pipe Elbow Insulation	PE		R		
Storage Room Behind Central Control	12 x 12 Floor Tile	F		G		No
Hallway ceiling at Central control	2x2 Ceiling Tile	C	0%		Yes	
R7 Lobby - West Stairwell	9 x 9 Floor Tile	F		G		No
Elevator Lobby & East Hallway	Textured Ceiling	C	20 - 30	G	Yes	
Lobby - Men,s Washroom	Plaster Ceiling	PL		G		No
Lobby - Men,s Washroom - Central Control Storage Closet	Plaster Ceiling & Walls	PL	2-5%		Yes	
R8 - Lobby - Women's Washroom Plumbing Chase	Pipe Elbow Insulation	PE		G		No
West Crawlspace	Pipe Elbow Insulation	PE	10%	G	Yes	
R9 - Southwest Elec/Telephone Room	Pipe Elbow Insulation	PE	10%	G	Yes	
West Stairwell	Ceiling & Wall Plaster	PL	0%		Yes	
West Men's Washroom	Ceiling Plaster	PL		G		No
West Women's Washroom	Ceiling and Wall Plaster	PL		G		No
<b>Main Floor</b>						
West Wing Office Area	Spray On Asbestos Above Ceiling	SO		G		No
	9 X 9 Floor Tile Below Carpet	F		G		No
	Wall Plaster	PL	0%		Yes	
West Wing Lobby	Textured Ceiling	PI		G		No
	Asbestos Spray-on Above Ceiling	SO		G		No

Application Type: AF- Fabric C - Ceiling Tile D - Ducting F - Flooring HB - Hardboard PE - Pipe Elbow Insulation PI - Pipe Insulation PL - Plaster SO - Spray On Legend TI - Tank Insulation TP Transite Pipe V - Vermiculite Condition: G - Good NR - Needs Repair R - Removed						
Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
R20 - West Air Shaft	Spray On Insulation (beams)	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R11 - West Stairwell	9 x 9 Floor Tile	F		G		No
R12 - East Stairwell	9 x 9 Floor Tile	F		G		No
Ceiling Area Above Courtyard Doors	Spray On Insulation	R				
Ceiling Area Above Northwest Exit Doors	Spray On Insulation	R				
Ceiling Area Above Northeast Exit Doors	Spray On Insulation	R				
West Wing - Restaurant	Texture Ceiling	R				
	Spray On Insulation	R				
East Wing Offices Area	Textured Ceiling	PL		G		No
	9 x 9 Floor Tile Below Carpet	F		G		No
	Wall Plaster	PL	0	.	Yes	
	Vermiculite Insulation (Room Divider Panels)	LF	<1%	G	Yes	
<b>Second Floor</b>						
Ceiling Areas	Textured Ceiling	R				
	Spray On Insulation Above Ceiling	R				
R13 - West Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R14 - Men's Washroom Plumbing Chase	Sray On Insulation	SO		G		No
	Pipe Elbow Insulation	PE		G		No
R15 - East Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
<b>Third Floor</b>						
Elevator Lobby	Textured Ceiling	PL		G		No
	Spray On Insulation Above Ceiling	C		G		No
	9 x 9 Floor Tile	SO		G		No
Men's Washroom	Textured Ceiling	PL		G		No
	Spray On Insulation Above Ceiling	C		G		No
	9 x 9 Floor Tile	SO		G		No
R16 - Men's Washroom Plumbing Chase	Spay On Insulation	SO		G		No
R27 - West Air Shaft	Spray on Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R18 - West Electrical Vault	Sray On Insulation	SO		G		No
	9 x 9 Floot Tile	F		G		No
West Stairwell	9 x 9 Floor Tile	F		G		No
East Stairwell	9 x 9 Floor Tile	F		G		No

Application Type: **AF- Fabric C - Ceiling Tile D - Ducting F - Flooring HB - Hardboard  
PE - Pipe Elbow Insulation PI - Pipe Insulation PL - Plaster SO - Spray On  
TI - Tank Insulation TP Transite Pipe V - Vermiculite**

**Legend**

Condition: **G - Good NR - Needs Repair R - Removed**

Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
R26 - East Air Shaft	Spray on Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R19 - East Electrical Vault	Spray On Insulation	SP		G		No
	9 x 9 Floor Tile	F		G		No
Women's Washroom	Textured Ceiling	PL		G		No
	Spray On Insulation Above Ceiling	C		G		No
	9 x 9 Floor Tile	SO		G		No
R17 - Women's Washroom Plumbing Chase	Spray On Insulation	SO		G		No
All Office Areas	Spray On Insulation Above Ceiling	SO		G		No
	9 x 9 Floor Tile Under Carpet	F		G		No
<b>Fourth Floor</b>						
Elevator Lobby	Textured Ceiling	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
	9 x 9 Floor Tile	F		G		No
Men's Washroom	Texture Ceiling	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
R21 - Men's Washroom Plumbing Chase	Spray On Insulation	SO		G		No
West Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R24 - West Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
West Stairwell	9 x 9 Floor Tile	F		G		No
East Stairwell	9 x 9 Floor Tile	F		G		No
R25 - East Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
East Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
Women' Washroom	Texture Ceiling	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
All Office Areas	9 x 9 Floot Tile Under Carpet	F		G		No
<b>Fifth Floor</b>						
Elevator Lobby Area	Textured Ceiling	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
	9 x 9 Floor Tile - Gray & White	F		G		No
Men's Washroom	Textured Ceilings	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
R28 - Men's Washroom Plumbing Chase	Spray On Insulation	SO		G		No
West Air Shaft	Spray On Insulation	SO		G		No
	Pipe & Pipe Elbow Insulation	PW		G		No

Application Type: AF- Fabric C - Ceiling Tile D - Ducting F - Flooring HB - Hardboard PE - Pipe Elbow Insulation PI - Pipe Insulation PL - Plaster SO - Spray On Legend TI - Tank Insulation TP Transite Pipe V - Vermiculite Condition: G - Good NR - Needs Repair R - Removed						
Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
R32 - West Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
West Stairwell	9 x 9 Floor Tile	F		G		No
East Stairwell	9 x 9 Floor Tile	F		G		No
R33 - East Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
East Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
Women's Washroom	Textured Ceilings	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
R29 - Women's Washroom Plumbing Chase	Spray On Insulation	SO		G		No
Cubicle Southwest	9 x 9 Floor Tile Under Carpet	F		G		No
All Office Areas	9 x 9 Floor Tile Under Carpet	F		G		No
<b>Sixth Floor</b>						
Elevator Lobby Area	Textured Ceiling	C		G		No
	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
Men's Washroom	Textured Ceiling	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
West Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
R30 - West Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
West Stairwell	9 x 9 Floor Tile	F		G		No
East Stairwell	9 x 9 Floor Tile	F		G		No
East Electrical Vault	Spray On Insulation	SO		G		No
	9 x 9 Floor Tile	F		G		No
R31 - East Air Shaft	Spray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
Women's Washroom	Textured Ceilings	C		G		No
	Spray On Insulation Above Ceiling	SO		G		No
R34 - Women's Washroom Plumbing Chase	Spray On Insulation	SO		G		No
	Pipe Elbow Insulation	PE		G		No
All Office Areas	9 x 9 Floor Tile Under Carpet	F		G		No
<b>Seventh Floor</b>						
Elevator Lobby Area	12 x 12 Floor Tile	F		G		No
West Stairwell	9 x 9 Floor Tile	F		G		No
East Stairwell	9 x 9 Floor Tile	F		G		No

Application Type: AF- Fabric C - Ceiling Tile D - Ducting F - Flooring HB - Hardboard PE - Pipe Elbow Insulation PI - Pipe Insulation PL - Plaster SO - Spray On Legend TI - Tank Insulation TP Transite Pipe V - Vermiculite Condition: G - Good NR - Needs Repair R - Removed						
Asbestos Location	Description	Application Type	Estimated %	Condition	Area Tested	
					Yes	No
Computer Room	Pipe Insulation Above Ceiling	PI		G		No
	Pipe Elbow Insulation Above Ceiling	PE		G		No
	Duct Insulation Above Ceiling	D		G		No
	12 x 12 Floor Tile Under Floor Grid	F		G		No
Supply Storage Room	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D		G		No
	12 x 12 FloorTile	F		G		No
Boiler Room	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D		G		No
	Perimeter Hard Board Sheating	HB		G		No
East Mechanical Room	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D		G		No
	Perimeter Hard Board Sheating	HB		G		No
West Mechanical Room	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D		G		No
	Perimeter Hard Board Sheating	HB		G		No
West Air Shaft	Sray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
East Air Shaft	Sray On Insulation	SO		G		No
	Pipe Insulation	PI		G		No
	Pipe Elbow Insulation	PE		G		No
	NOTE: spray on insulation on roof deck is cellulose					
<b>Penthouse (8th Floor)</b>	Pipe Elbow Insulation	PE		G		No
	Duct Insulation	D	0%	G	Yes	No

Notes: All vinyl floor tile installed before 1990 may contain asbestos and therefore must be treated as an asbestos containing material  
Vermiculite insulation may contain pockets of asbestos and therefore all vermiculite must be treated as an asbestos containing material  
There may be asbestos containing materials present that were not located during building inspections