




PHOTOGRAPH #1: FACING NORTH, SHOWING DAMAGED BLOCKS FROM SECTION A



PHOTOGRAPH #2: FACING NORTHWEST, SHOWING DAMAGED BLOCKS FROM SECTION B




PHOTOGRAPH #3: FACING NORTHWEST, SHOWING DAMAGED BLOCKS FROM SECTION C



PHOTOGRAPH #4: FACING WEST, SHOWING DAMAGED BLOCKS FROM SECTION D



PHOTOGRAPH #5: FACING SOUTHWEST, SHOWING DAMAGED BLOCK FROM SECTION E



PHOTOGRAPH #6: FACING WEST TO NORTHWEST, SHOWING DAMAGED BLOCKS FROM SECTION F.

LEGEND

No.	DATE	ISSUE /REVISION
0	Aug 6/14	issue for tender

ENG-TECH
CONSULTING LIMITED
6 - 854 Marion Street
Winnipeg, MB R2J 0K4
Phone: (204) 233-1694
Fax: (204) 235-1579

ENG. STAMP:

CLIENT:
CITY OF WINNIPEG

PROJECT:
**DYKE REPAIR - 32 LORD AVENUE,
WINNIPEG, MANITOBA**

DWG DESCRIPTION:
PHOTOGRAPHS 1-6

SCALE:
N/A

DRAWN BY:
ALH

DATE:
AUGUST 2014

FILE No.:
14-217-02

CLIENT DWG/FIG. No.:

ENG-TECH DWG/FIG. No.:
2

NO.: