

Site 1 – East site looking west towards bridge and chamber site



Site 1 – East chamber site looking north



Site 1 – East chamber site looking east from bottom of bridge



Site 1 – East chamber interior - existing cross and 300 mm offtake



Site 1 – East chamber interior - 600 feeder main



Site 1 – West chamber site looking east



Site 1 – West chamber site top of crossing chamber



Site 1 – West chamber interior - existing side-outlet elbow with welded brace



Site 2 – North chamber site looking south



Site 2 – North chamber access.



Site 2 – South chamber site looking south



Site 2 – South chamber site looking north



Site 3 – North site



Site 3 – South site



Site 3 – Force Main at underside of bridge



Site 3 – Force main at underside of bridge