ASBESTOS INVENTORY CONTROL



Planning, Property and Development Department Municipal Accommodations Division 4th Floor - 185 King Street • Winnipeg, MB • R3B 1J1

Building Name:	Cornish Library	Inspectio	n Date:	July 6, 2017						
Building Code:	LB-02	Inspected	By:	Will Deller & Ryan Matthews						
Building Address:	20 WestGate	Construct	tion Date:	1914						
Material Location	Material Description	Drawing Label	Material Condition	Testing Status	Date M/Y	Test %	Est. %			
Main Floor										
Front Entrance	Wall Plaster	PL	Good				0			
	Ceiling Plaster	PL	Good							
Main Floor	9x9 Floor Tile - Under Carpet	F9	Good							
	Ceiling Plaster	PL	Good							
Basement										
Back Stairwell	12x12 Floor Tile	F12	Good	TESTED	May'12	3				
	9x9 Floor Tile	F9	Needs Repair							
Chess Room	9x9 Floor Tile	F9	Removed		Feb/'11					
	Ceiling Plaster	PL	Good							
	Wall Plaster	PL	Good	TESTED	Jan/'11	0				
Hallway	9x9 Floor Tile	F9	Removed		Feb/'11					
	Ceiling Plaster	PL	Good							
	Wall Plaster	PL	Good				0			
Children Reading Room	9x9 Floor Tile	F9	Good							
	Wall Plaster	PL	Good				0			
Staff Room	9x9 Floor Tile	F9	Needs Repair							
	Ceiling Plaster	PL	Good							
	Wall Plaster	PL	Good				0			
Washrooms (Men & Women's)	Ceiling Plaster	PL	Good							
	Wall Plaster	PL	Good				0			
Storage Room	Ceiling Plaster	PL	Good							
	Wall Plaster	PL	Good				0			
	ATTIC HAS BEEN INSPECTED AND DOES NOT CONTAIN ACM. Sept 02/ 2014. REM.									

NOTES:

Г

		Drawing	Material	Τ	Testing	Date	Test	Est.
Material Location	Material Description	Label	Condition		Status	M/Y	%	%
1. Asbestos inspections and inventory updates are conducted annually.								
2. There may be asbestos containing materials present that were not located during asbestos inspections.								
3. Floor tile and sheet flooring installed before 1990 may contain asbestos and must be treated as an asbestos containing material.					3-C	17		
Vermiculite insulation may contain pocket	s of asbestos. All vermiculite insulation must be treated as an asbestos conta	ining material.						

Floor tile and sheet flooring installed before 1990 may contain asbestos and must be treated as an asbestos containing material.
Vermiculite insulation may contain pockets of asbestos. All vermiculite insulation must be treated as an asbestos containing material.

5. For asbestos related inquiries, call Central Control at 986-2382



