

Template Version: C520180312 - C Bldg LR

# APPENDIX C SHOAL LAKE AQUEDUCT INTAKE RESIDENCE UPGRADE – SITE PHOTOS

Staffhouse Room 109 Ceiling



Staffhouse Room 111 – Existing Window to Remove and Infill



## Staffhouse Room 102 – Clerestory Windows




Staffhouse Room 102 - Window Sill



## Staffhouse Room 102 Windows



Staffhouse Room 117 Window




**Staffhouse 117 Exterior Door** 



Staffhouse Veranda Screens



Staffhouse Fireplace



### **Staffhouse Front Entrance**



Staffhouse Room 102 Windows (Exterior)



Staffhouse Exterior Grilles to be Removed



**Staffhouse Secondary Front Entrance** 



 ${\bf Staffhouse\ Condenser-Northern\ Exposure}$ 




Staffhouse Room 110 Exterior Door



Staffhouse East Elevation Room 120 to 128




Staffhouse Fireplace - Exterior




Staffhouse Veranda Screens - Exterior



Operator's Residence – Existing Interface of Siding and Deck



**Operator Residence Flooring** 




Operator Residence – Electrical Panel









**Operator Residence Furnace** 





### Lakeview Residence –Exteriors Photos










#### Lakeview Residence - Electrical Panel
















#### Lakeview Residence - Interior







Lakeview Residence - Furnace



Foreman's Residence – Exterior















Foreman's Residence Electrical Panel and Subpanel











Staffhouse Attic









**End of Photos**