

APPENDIX F – 2019 CRANE INSPECTION REPORT
Hurst Pumping Station

Required Sections

Required Sections


Please check off all applicable inspections for this job.

- Travel Time
- Shop Time
- Shipping
- Repairs Request
- Crane Service & Inspection
- Main Hoist Service & Inspection
- Main Hoist Rope Service & Inspection
- Main Hoist Trolley Service & Inspection
- Aux Hoist Rope Service & Inspection
- Aux Hoist Trolley Service & Inspection
- Aux Hoist Service & Inspection
- Aux Device Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection
- Main Hoist Trolley Service & Inspection

Site Start Time

04/30/2019 07:30:38 AM

Site Location



Job Title

A19-153 - COW - Pump Station Inspections

Job Number

MANDATORY FIELD

A19-153

"Job Type"
MANDATORY FIELD

R.S.I.-A (Regulatory Safety Inspection - ANNUAL)

Client

CoW - Pump Lagemoder

Office Work Request Information & Description

Inspections Pumping Station Hurst Way / Waverley St
8:30 am

Requested By:

- Shawn
- Rod
- June
- Jose

Crane Identification

Field Name/Number

Hurst pumphouse

Crane Model

Whiting

Crane Serial Number

8428

Main Hoist Model

Northern

Crane Identification Image



Technician/Office Personnel

Select all applicable personnel

- bobf@advancecraneltd.com
- dave@advancecraneltd.com
- chris@advancecraneltd.com
- jeff@advancecraneltd.com

Safety Set Up

Please check off your completed Safety Forms as required

- Daily Hazard Assessment
- Fall Protection Equipment Pre-Use Checklist
- Ladder Pre-Use Checklist
- Aerial or Scissor Lift Pre-Use Checklist
- Weekly Company Vehicle Inspection Check List
- Monthly Fire Extinguisher

Crane Service & Inspection

Approved for Use?

- Yes
- No

Make/Model/Serial Number

Only enter if the model # is different from field above

Whiting/8428

Picture of Make/Model/Serial Number



Type

Trdg

Capacity

7.5 tons

Inspected?

- Yes
- No

Number of Defects Found

1

Client Copy - Description of defects found. (Please be as specific as possible)

1- No directional sign on Bridge . Crane requires directional sign on bottom of bridge girder that corresponds to remote controller.

Adjusted?

- Yes
- No

Repaired?

- Yes
- No

Client Copy - Description of completed service work, adjustments or repairs

Greased all bridge drive line shaft bearings and drive wheel bearings. Checked oil level in gearbox, level is good.
*could not grease southeast bridge wheel bearings, inaccessible

Defect/Adjustment/Repair Image



Main Hoist Service & Inspection

Approved for Use?

- Yes
- No

Make/Model/Serial Number

Only enter if the model # is different from auto-filled form above

Northern 4/4181

Picture of Make/Model/Serial Number



Type

Trdg

Capacity

7.5 tons

Inspected?

- Yes
- No

Number of Defects Found

1

Description of defects found. (Please be as specific as possible)

1- load capacity on hook block is not clear . Hook block requires clear load capacity sign. (7.5 tons)

Adjusted?

Yes
 No

Repaired?

Yes
 No

Description of completed service work, adjustments or repairs

Greased hook block and upper sheaves. Checked oil level in hoist gearbox, level is good.

Defect/Adjustment/Repair Image



Main Hoist Rope Service & Inspection

Approved for Use?

Yes
 No

Inspected?

Yes
 No

Number of Defects Found

0

Adjusted?

Yes
 No

Repaired?

Yes
 No

Description of completed service work, adjustments or repairs

Cleaned areas of rope for inspection. Lubed wire rope and drum.

Main Hoist Trolley Service & Inspection

Approved for Use?

- Yes
- No

Make/Model/Serial Number

Only enter if the model # is different from auto-filled form above

Northern

Type

Trdg

Capacity

7.5 tons

Inspected?

- Yes
- No

Number of Defects Found

0

Adjusted?

- Yes
- No

Repaired?

- Yes
- No

Description of completed service work, adjustments or repairs

Greased all wheel bearings. Checked gearbox oil level, level is good.

Field Work Description

MANDATORY FIELD - Field Personnel please put your notes of completed work here

Inspection complete. Crane fit for service.

Parts & Consumables

1 can- ZEP2000
1 tube- EP1 grease

Repairs Request

Lift Required?

- Yes
- No

Description of completed service work, adjustments or repairs

Crane Service | Client Copy - Description of completed service work, adjustments or repairs.

Please insert the number of technicians, hours & parts required.

1- No directional sign on Bridge . Crane requires directional sign on bottom of bridge girder that corresponds to remote controller.

Main Hoist Service - Description of completed service work, adjustments or repairs.

Please insert the number of technicians, hours & parts required.

1- load capacity on hook block is not clear . Hook block requires clear load capacity sign. (7.5 tons) 1 tech/1hr for all repairs

Inspector Signature



Inspector Name

Chris Webster

Client Signature



Client Name

Randy K

Safety Tear Down

Please check and indicate that you have completed the following before leaving the job site.

- All tools and rigging has been removed and accounted for.
- All safety barricades, cones and marking tape has been removed and is accounted for.
- All locks have been removed.
- All material and parts have been removed and any required clean-up of the crane or lift is complete.
- The client has been informed that the job is complete and is satisfied.

Job Status


MANDATORY FIELD

Field - COMPLETE

Site Stop Time

04/30/2019 12:00:04 PM

Site Location



Calculated Total Time

Calculated Total Time

4:29:1766

Man Hours Details

Site start/stop times include travel

Time Card

arworkhours@gmail.com;info@advancecraneltd.com;ltenumah@siriustechnologies.ca;

Time card report

Office Report

info@advancecraneltd.com

Office Report

Client Report

info@advancecraneltd.com

Client Report

Powered by www.doForms.com