



Figure 1 - Site 1: Bannatyne S-MA20016321 - General Conditions



Figure 2 - Site 1: Bannatyne S-MA20016321 – Encrustation and Roots



Figure 3 - Site 1: Bannatyne S-MA20016321 – General Condition



Figure 4 - Site 1: Bannatyne S-MA20016321 – Encrustation and Roots



Figure 5 - Site 1: Bannatyne S-MA20016321 – Downstream Manhole



Figure 6 - Site 2: Bannatyne S-MA20018612 - General Condition



Figure 7 - Site 2: Bannatyne S-MA20018612 - General Condition w/ encrusted service



Figure 8 - Site 2: Bannatyne S-MA20018612 - General Condition w/ intruding service and encrustation



Figure 9 - Site 2: Bannatyne S-MA20018612 - General Condition w/ encrusted service



Figure 10 - Site 3: Logan Av S-MA20019010 - General Conditions



Figure 11 - Site 3: Logan Av S-MA20019010 - General Conditions w/ missing grout



Figure 12 - Site 3: Logan Av S-MA20019010 - General Conditions @ DS Manhole



Figure 13 - Site 4: Metcalfe Av S-MA50004315 - General Conditions w/ Surface Spalling



Figure 14 - Site 4: Metcalfe Av S-MA50004315 - General Conditions w/ Surface Spalling



Figure 15 - Site 4: Metcalfe Av S-MA50004316 - General Conditions w/ Surface Spalling



Figure 16 - Site 4: Metcalfe Av S-MA50004316 - General Conditions w/ Surface Spalling





Figure 17 - Site 4: Metcalfe Av S-MA50004316 - General Conditions w/ Surface Spalling



Figure 18 - Site 4: Metcalfe Av S-MA50004316 - Instrumentation and Cabling at S-MH50003713



Figure 19 - Site 4: St Mary's Rd S-MA70003174 – General Conditions w/ Surface Spalling



Figure 20 - Site 4: St Mary's Rd S-MA70003174 – General Conditions



Figure 21 - Site 4: St Mary's Rd S-MA70003174 – General Conditions w/ Surface Spalling