



Figure 1: View from West Side of Deacon Pump Floor



Figure 2: View of Pipe Bend Reducer and Blind Flange to be Removed



Figure 3: View of Work Area at Pipe Bend Reducer Facing North



Figure 4: View of Work Area at Pipe Bend Reducer Facing South