

# **APPENDIX 'B'**

## **SITE PHOTOS**

**Branch I Aqueduct Underdrain Outfall Repairs**

**Tender 694-2024 - Appendix B – Site Photos**



*Figure 1 – Rue Plinguet Underdrain Outfall Site, looking west.*



*Figure 2 – Rue Plinguet Underdrain Outfall- Seine River, looking southwest.*

**Branch I Aqueduct Underdrain Outfall Repairs**

**Tender 694-2024 - Appendix B – Site Photos**



*Figure 3 – Rue Plinguet Combined Sewer Outfall, looking east.*



*Figure 4 -Avenue Tache UMH110-0001, looking north.*

**Branch I Aqueduct Underdrain Outfall Repairs**

**Tender 694-2024 - Appendix B – Site Photos**



*Figure 5 – Avenue Tache Underdrain Outfall Site, looking northwest.*



*Figure 6 - Avenue Tache Underdrain Outfall – Vent Pipes, looking north.*

Branch I Aqueduct Underdrain Outfall Repairs

Tender 694-2024 - Appendix B – Site Photos



*Figure 7 – Rue Notre Dame Underdrain Outfall, looking east.*



*Figure 8 – Rue Notre Dame Underdrain, looking east at headwall.*

**Branch I Aqueduct Underdrain Outfall Repairs**

**Tender 694-2024 - Appendix B – Site Photos**



*Figure 9 – Rue Notre Dame Underdrain Outfall, looking east.*



*Figure 10 – Rue Notre Dame Underdrain Outfall, looking west.*

**Branch I Aqueduct Underdrain Outfall Repairs**

**Tender 694-2024 - Appendix B – Site Photos**



*Figure 11 – Rue Notre Dame Underdrain Outfall Site, looking west.*



*Figure 12 – S-MH50008084 (Archibald Street & Rue Notre Dame) underdrain and sewer connections.*

Branch I Aqueduct Underdrain Outfall Repairs

Tender 694-2024 - Appendix B – Site Photos



Figure 13 – UMH119-0137 (Dawson Rd) existing connections and floor drain.



Figure 14 – AQ-U00000181 (GWWD Railyard) void around missing underdrain