

## **APPENDIX B**

### **SITE PHOTOGRAPHS**



**Photo 1: Roland Outfall – Looking west towards chamber at upper bank**



**Photo 2: Roland Outfall – Looking northeast towards Watt Street from parking lot**



**Photo 3: Roland Outfall – Looking south from upper bank**



**Photo 4: Roland Outfall – Looking north towards chamber at upper bank**



**Photo 5: Roland Outfall – Looking north along upper bank**



**Photo 6: Roland Outfall – Looking north along mid bank**





**Photo 7: Roland Outfall – Looking south along mid bank**



**Photo 8: Roland Outfall – Looking south west along mid bank**




**Photo 9: Roland Outfall – Looking north along mid bank**



**Photo 10: Roland Outfall – Looking north along mid to lower bank**



**Photo 11: Roland Outfall – Looking south along mid to lower bank**



**Photo 12: Roland Outfall – Emergency repair/slip joint. Looking upstream towards 1350 SRS connection and chamber**





**Photo 13: Roland Outfall – emergency repair/slip joint**



**Photo 14: Roland Outfall – emergency repair/slip joint (photo taken looking upstream from outlet)**



**Photo 15: Roland Outfall – small sinkhole observed at grade along mid to upper bank**



**Photo 16: Roland Outfall – looking north along lower bank**



**Photo 17: Roland Outfall – looking south along lower bank**



**Photo 18: Roland Outfall – looking east from upper bank towards pumping station**