ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

BUILDING NAME: SEVEN OAKS POOL	**INSPECTION DATE**: March 21/2005
BUILDING CODE: PI-01	**INSPECTED BY**: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 444 ADSUM DRIVE	Year Built: 1977

LEGEND-
Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster **TI**-Tank Insulation **C**-Ceiling **F**-Flooring
Condition: **G**-Good **NR**-Need Repair
Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
UPPER FLOOR LEVEL							
Upper Floor Mechanical Room	Pipe Elbows	PW		G	2Y		no
Upper Floor Instructor Office	Ceiling Tile	C	0%	G	N/A	yes	
BASEMENT LEVEL							
Staff Room	Pipe Elbows	PW		G	2Y		no
Entrance to Women's Locker Room @ ceiling	Pipe Elbows	PW		G	2Y		no
Women's Locker Room	Pipe Elbows	PW		G	2Y		no
Men's Locker Room	Pipe Elbows	PW		G	2Y		no
Engineers Office	Pipe Elbows	PW		G	2Y		no
Filter Room	Pipe Elbows	PW		G	2Y		no
Boiler Room	Pipe Elbows	PW		G	2Y		no
East Tunnel	Pipe Elbows	PW		G	2Y		no
Spare Parts Room	Pipe Elbows	PW		G	2Y		no
West Tunnel	Pipe Elbows	PW		G	2Y		no
Corridor to Boiler Room	Pipe Elbows	PW		G	2Y		no