



280-2007 ADDENDUM 1

REPAIR GLULAM BEAMS - ROLAND MICHENER ARENA - 1121
WABASHA AVENUE

URGENT

**PLEASE FORWARD THIS DOCUMENT TO
WHOEVER IS IN POSSESSION OF THE BID
OPPORTUNITY**

ISSUED: May 17, 2007
BY: Corrine Evason, C.P.P.
TELEPHONE NO. (204) 986-8034

**THIS ADDENDUM SHALL BE INCORPORATED
INTO THE BID OPPORTUNITY AND SHALL
FORM A PART OF THE CONTRACT
DOCUMENTS**

Template Version: A20070419

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.

PART A – BID SUBMISSION

Replace: Form B: Prices Bid Submission with 280-2007 Addendum 1 - Bid Submission. The following is a summary of changes incorporated in the replacement Bid Submission:

Change in format.

280-2007 NMS Format Specifications-06100.DOC

Revise 3.7.1 to read:

- .1 Contractor shall note that deterioration of the glulam beam faces and ends is generally different on each face and at the beam ends. Each beam shall be individually assessed and before starting to remove damaged material the Contract Administrator shall be advised of the prevailing conditions. The Contractor shall anticipate having to Work on **both** beam faces at a time, in some cases with a delay between operations while resin materials and repairs achieve satisfactory strength.