



425-2010 ADDENDUM #3

REFURBISH FAN UNITS – 510 MAIN

URGENT

**PLEASE FORWARD THIS DOCUMENT TO
WHOEVER IS IN POSSESSION OF THE BID
OPPORTUNITY**

ISSUED: August 4, 2010
BY: Kathy Roberts
TELEPHONE NO. (204) 470-7380

**THIS ADDENDUM SHALL BE INCORPORATED
INTO THE BID OPPORTUNITY AND SHALL
FORM A PART OF THE CONTRACT
DOCUMENTS**

Template Version: A20070419

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.

PART D – SUPPLEMENTAL CONDITIONS

Revise: D2.2(b) to read: Description of Work for each fan unit:

- (i) Replace bearings on fan only, (not on motor). Retighten bearing set screws after 300 hours of fan operation.
- (ii) Replace belts.
- (iii) Replace pulleys on both the fan and the motor.
- (iv) Check and trim balance unit.
- (v) Clean fan assembly.
- (vi) Contractor may re-use existing bolts if they are in good condition. If bolts are in poor condition or missing, provide new bolts.