



467-2022 ADDENDUM 2

PROFESSIONAL CONSULTING SERVICES FOR PUMP STATIONS CHLORINE SYSTEM UPGRADES

URGENT

**PLEASE FORWARD THIS DOCUMENT TO
WHOEVER IS IN POSSESSION OF THE
BID/PROPOSAL**

ISSUED: September 20, 2022
BY: Matthew Skinner, P.Eng.
TELEPHONE NO. 204 250-3539

**THIS ADDENDUM SHALL BE INCORPORATED
INTO THE BID/PROPOSAL AND SHALL FORM
A PART OF THE CONTRACT DOCUMENTS**

Template Version: Add 2021-03-05

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid/Proposal, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid/Proposal may render your Bid/Proposal non-responsive.

ADDITIONAL CONFIDENTIAL DOCUMENTS REFERENCED IN THE ADDENDUM CAN BE RETRIEVED FROM THE SECURE LINK EMAILED PREVIOUSLY. PLEASE CONTACT THE CONTRACT ADMINISTRATOR AT 204 250-3539 FOR ASSISTANCE.

FORM B

Revise: Spec. Ref. for item 18. Training to read: D13.17.
Revise: Spec. Ref. for item 20: Contract Closeout to read: D7.13, D7.15, D15.9, D17.

APPENDICES

Appendix_B The following documents are available for review by request to the Project Manager after the completion of a Non-Disclosure Agreement:

Add:

	Hurst Regional Pumping Station Cooling Upgrades Geotechnical Report	
11.1	Author: Trek	Geotechnical assessment of the soil conditions at Hurst RPS for the installation of gas engine cooling upgraded
	Published: 2021	

Questions and Answers:

- Q1: We would like clarification as to whether the McPhillips parking lot upgrades involve simply modifying the parking lot to accommodate pads for the scrubber, make-up air unit, and vestibule? If this is the case, are curbs and/or paint markings around the new pads expected to be adequate? Or would this involve expanding or making a new parking lot? If this is the case, can you roughly quantify the size of the expansion?
- A1: The extent of the parking lot expansion at the McPhillips RPS will depend on the size and location of the new equipment. For instance, if the new equipment displaces two existing parking spots, then the parking lot will need to be expanded to accommodate two new stalls to make up for the lost parking capacity.