



ASBESTOS INVENTORY CONTROL

BUILDING SERVICES DIVISION

Bronx Community Centre	INSPECTION DATE: May 26, 2006
BUILDING CODE: C.C. 009	INSPECTED BY: Karl Bauch & Jayson Cyncora
BUILDING ADDRESS: 131 Chelsea Place	Construction Date: 1950

LEGEND- Application Type: **PW**-Pipe Wrap **SO**-Spray On **HB**-Hardboard **EN**-Encapsulated **R**-Removed **PL**-Plaster
TI-Tank Insulation **C**-Ceiling **F**-Flooring
 Condition: **G**-Good **NR**-Need Repair
 Inspection Frequency: **B**-Per 6 Months **Y**-Yearly **2Y**-Two Years **5Y**-Five Years

Asbestos Location	Description	Application Type	Estimated %	General Condition	Inspection Frequency	Area Tested	
						Yes	No
Utility Room	Water line elbow wrap	PW		G	2Y		No
Furnace room	Water line elbow wrap	PW		G	2Y		No
	Block walls randomly inspected & appear to be empty (Do not contain vermiculite insulation)						

Note:

- All vinyl floor tile installed before 1990 may contain asbestos and therefore must be treated as an asbestos containing material
- Vermiculite insulation may contain pockets of asbestos and therefore all vermiculite must be treated as an asbestos containing material
- There may be asbestos containing materials present that were not located during building inspections
- Any asbestos related concerns should be directed to Bruce Kazun 794-4409 (alternate Robert Haglund 986-6047)