

A

1

power wire brush clean top of existing glulam beam  
(to be inspected prior to new repairs installed)

new 2x12 (DF #1) laminations

2'-2"±

1'-5 5/8"

4 7/8"

4 7/8"±

6"

8"

6"

8"

6"

1'-15 5/8"

8" min staggered joints

8"

random repairs to be determined on site

- route out existing lamination to solid wood
- install similar sized lamination (DF #1) c/w epoxy resin adhesive

New Glulam Beam Repair Methods

Scale: 1" = 1'-0"

# SK-5

Glulam Beam Repairs  
 Roland Michener Arena  
 1121 Wabasha Street  
 Winnipeg, MB R2C 1G6



**GC ENGINEERING LTD.**  
 675 ELM ST.  
 WINNIPEG MB R3M 3N8  
 PH 793-3948 FAX 487-4616  
 EMAIL CALGRAY@MTS.NET