



# 209-2011 ADDENDUM 3

## SEWPCC ESSENTIAL SYSTEM UPGRADES

### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO  
WHOEVER IS IN POSSESSION OF THE BID  
OPPORTUNITY**

ISSUED: May 9, 2011  
BY: Charles Cong  
TELEPHONE NO. (204) 786-8080

**THIS ADDENDUM SHALL BE INCORPORATED  
INTO THE BID OPPORTUNITY AND SHALL  
FORM A PART OF THE CONTRACT  
DOCUMENTS**

Template Version: A20070419

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid may render your Bid non-responsive.**

### **PART A – BID SUBMISSION**

Replace: 209-2011\_Bid\_Submission with 209-2011\_Addendum\_3\_Bid\_Submission. The following is a summary of changes incorporated in the replacement Bid Submission:

Form B: Corrected the specification section for Line 8.

Form B: Corrected the description for Line 11.

Form B: Added Line 16.

Form G2: Modified the expiry date.

### **PART E – SPECIFICATIONS**

Delete: E3.12 (b)

Add: E3.14 DCS Hardware

(a) Replace the existing MFP processor modules with redundant BRC400 processor modules in PCU-SA, including:

(i) 2 x Harmony Bridge Controller with Expanded Memory (PHCBRC40000000)

(ii) Bridge Controller Redundancy Cable – 0.2 m (PMKHRMBRC3000A)

(iii) Existing MFP processor modules are to be turned over to the City.

Clarification of E3.14: The original Bid Opportunity specified that the optimization of the existing logic was required. This requirement has been eliminated and replaced by the requirement to replace the existing processor modules with more powerful BRC 400 processors.

Add Section 26 05 01 Clause 1.10.4

Cable Identification: Supply and install lamacoid type cable identification tags for all cables. Install identification tag at both ends.

Replace: Section 26 05 32 with 209-2011\_Addendum\_3\_Section 26 05 32.

Add: 209-2011\_Addendum\_3\_Section 26 27 26.