

Image 2014 DigitalGlobe


EXISTING PLAYGROUND

 $\langle 1 \rangle$

(1)

EXISTING BASEBALL DIAMOND

MEDICINE WHEEL



DEMOLITION AND UNDERGROUND SERVICE GENERAL NOTES

- CONDUCT ALL WORK IN ACCORDANCE WITH THE SPECIFICATIONS.
- 2) ALL SERVICES SHOWN ARE BASED ON THE BEST INFORMATION AVAILABLE. NO GUARANTEE IS GIVEN THAT LOCATIONS ARE EXACT. CONFIRMATION OF EXISTENCE AND EXACT LOCATION OF ALL SERVICES MUST BE OBTAINED FROM THE INDIVIDUAL UTILITIES BEFORE PROCEEDING WITH CONSTRUCTION. ANY ENCUMBRANCES SHALL BE REPORTED TO THE CONTRACT ADMINISTRATOR IMMEDIATELY.
- 3) ENSURE THE LOCATION OF ALL EXISTING SERVICES BOTH OLD AND RECENTLY INSTALLED ARE CLEARLY LOCATED ON SITE PRIOR TO CONSTRUCTION. THE CONTRACTOR WILL BE RESPONSIBLE FOR LOCATING AND REPAIRING ALL DAMAGE CAUSED TO SERVICES DURING CONSTRUCTION.
- 4) COMPLETE INDIVIDUAL TREE PROTECTION AND ERECT AND MAINTAIN TREE PROTECTION BARRIERS AND SAFETY SIGNAGE FOR THE DURATION OF CONSTRUCTION AS PER THE SPECIFICATIONS.
- 5) ALL DIMENSIONS ARE IN METERS UNLESS OTHERWISE SPECIFIED.
- 6) ALL DAMAGE TO ADJACENT PROPERTY CAUSED BY CONSTRUCTION ACTIVITY MUST BE REPAIRED BY THE CONTRACTOR PRIOR TO PROJECT COMPLETION.
- REPORT ANY DISCREPANCIES TO THE CONTRACT ADMINISTRATOR IMMEDIATELY.
- 8) CONDUIT CONTAINING FIBRE OPTIC CABLES MUST BE EXCAVATED IN ACCORDANCE WITH UTILITY'S EXPRESSED REQUIREMENTS. THE CONTRACTOR SHALL CONTACT THE UTILITY AT LEAST SEVEN DAYS PRIOR TO EXCAVATION.
- 10) REPAIR ANY ADDITIONAL DAMAGE TO HARD AND SOFT SURFACES CAUSED BY CONSTRUCTION ACTIVITIES AT NO ADDITIONAL COST TO THE CITY OF WINNIPEG. REPAIR ALL DAMAGE AS CLOSELY AS POSSIBLE TO ORIGINAL CONDITION.

LEGEND

	EXCAVATE AND REMOVE EXISTING SOD AND ALL BASE AND SUB-BASE MATERIALS
	PROPERTY LINE
	LIMIT OF WORK
\bigotimes	EXISTING LIGHT STAND
	EXISTING DRAINAGE LINE (APPROXIMATE)
	EXISTING TREE (TO REMAIN)
$\langle 1 \rangle$	COTECT EXISTING INDIVIDUAL TREES TO REMAIN ACCORDANCE WITH SPECIFICATIONS
	OTECT EXISTING GROUPS OF TREES/SHRUBS O REMAIN WITH SNOW FENCING IN ACCORDANCE TH SPECIFICATIONS
AN	ISTING CATCH BASIN. VERIFY INVERT LOCATION ID ELEVATION PRIOR TO STARTING ANY DNSTRUCTION OR REMOVAL.
	DNSTRUCTION SITE ACCESS
5 EX	SISTING BUS STOP

3	Revisions	2014/01/30	cow
2	Internal	2014/01/13	
1	66 %	2013/12/20	cow
	Revisions	Date	Ву
March 20, 2	2014 1:400		
Designed By	Drawn By	Checked By	
CN/CWM	CWM	CN	
Seals			
LOMBARD NG 287 Taché Av Winnipeg, Ma	DRTH GROUP e. nitoba R2H 2A1 -3896 <i>Tel:</i> (204) 947-5	696	
LOMBARD NG 287 Taché Av Winnipeg, Ma <i>Tel:</i> (204) 943 Winnipeg THE CITY O Planning, Prope Planning and La	re. nitoba R2H 2A1	artment	

SHAUGHNESSY PARK - DEMOLITION & EXISTING CONDITIONS

Sheet Title