

INSPECTION AND TECHNICAL SERVICES MB
508 - 401 YORK AVENUE,
WINNIPEG, MB R3C 0P8
PHONE (204) FAX (204)
HTTP://FIRECOMM.GOV.MB.CA/ITSM_MAIN.HTML

CITY OF WINNIPEG CORP FINANCE 4TH FLR.,510 MAIN ST., WINNIPEG, MB R3B 1B9 MB Elevator # 3433 Elevator Type: HYDRAULIC Location : CENTENNIAL LIBRARY 251 DONALD ST WINNIPEG

The Elevating Device located at : 251 DONALD ST, in the City of WINNIPEG, was inspected on by our Inspector
The following conditions were observed that require attention at this time:
For systems where the part of cylinder and / or piping is not exposed for visible inspection, a written record shall be kept of the quantity of hydraulic fluid added to the system and emptied from leakage collection containers and pans. The written record shall be kept in the machine room. When the quantity of hydraulic fliud loss cannot be accounted for, the test specified in 8.11.3.2.1 and 8.11.3.2.2 shall be made - 8.6.5.7 B44 07.
Repair the hoistway access key switch at top floor.
The elevator hoisting machine seals, gaskets and caps shall be repaired and maintained to prevent oil leaks - 12.2.1 B44 M90.
This elevator will remain on a 6 month permit until all outstanding orders have been completed.
The above instructions must be completed by and the above Branch notified accordingly.

888-2015_251_Donald_Escalator_No_03_Improvement_Order_MB_Elevator_No_3433-R00



INSPECTION AND TECHNICAL SERVICES MB 508 - 401 YORK AVENUE, WINNIPEG, MB R3C 0P8 PHONE (204) 945-3398, FAX (204) 948-2309 HTTP://FIRECOMM.GOV.MB.CA/ITSM_MAIN.HTML

Please notify our office in writing when the work orders have been completed.

It is the owner's responsibility to inform our Branch of all changes regarding management and ownership and possession date in order that our record may be amended accordingly.

If you have any questions regarding this report, please contact me at (204)

Report Submitted by:

Inspection and Technical Services MB

Phone number: (204)

Fax number :

Email: