

APPENDIX B - TABLE E10.2 : SITE SPECIFIC MANHOLE CONDITIONS AND REPAIR REQUIREMENTS

	STREET_NAME	LOCATION_DETAILS	MANHOLE_ID	REPAIRS REQUIRED
1	Riviera Avenue	MH at Riviera Crescent	S-MH70010295	Grout 0.15m below reducer under frame
2	Pembina Highway	1st MH S of Riverwood Ave	S-MH60014965	Grout 0.1m below frame
3	Pembina Highway	1st MH N of Riverwood Ave	S-MH60003309	Install 76mm manhole riser ring (AP-010)
4	Kelvin Boulevard	2nd MH N of Mountbatten Ave	S-MH70010295	Install 76mm manhole riser ring (AP-010), replace cracked frame (AP-006) and cover (AP-007)
5	Kelvin Boulevard	4th MH N of Moutbatten Ave	S-MH60003302	Grout 0.1m below frame
6	Roblin Boulevard	MH at WPL Pepperloaf Cr	S-MH60002383	Install benching in MH