

910-2022 ADDENDUM 1

2022 OUTFALL PROGRAM – REHABILITATION AND CLEANINGS

URGENT

PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE BID/PROPOSAL ISSUED: December 13, 2022 BY: Nicole Vidal, C.E.T. TELEPHONE NO. 204 896-1209

THIS ADDENDUM SHALL BE INCORPORATED INTO THE BID/PROPOSAL AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS Template Version: Add 2021-03-05

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid/Proposal, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid/Proposal may render your Bid/Proposal non-responsive.

FORM B: PRICES

Replace: 910-2022_eForm_B-Prices with 910-2022_Addendum_1- Form_B-Prices. The following is a summary of changes incorporated in the replacement Bid/Proposal Submission:

Form B(R1): Revise Item H3 – Approx. Quantity.

Revise Item H5 – Approx. Quantity.

Page numbering on some forms may be changed as a result.

PART B – BIDDING PROCEDURES

Revise: B11.2 to read: (a) Uni-Jet Industrial Pipe Services

(i) CCTV Services

(b) Tri Core Projects Ltd.

(i) Constructability Review of Rivergate Drive Outfall HDD Cleaning

PART D - SUPPLEMENTAL CONDITIONS

Add: D2.3(d) Further to D2.3(b), the level of sediment and debris within the Ferry Road Outfall and Southbridge Drive Outfall is unknown given that the pipe outlets are either fully and/or partially submerged. HDD Cleaning will be at the discretion and direction of the Contract Administrator once temporary cofferdams and de-watering work is completed and level of sediment/debris within the pipes are verified in field.

PART E - SPECIFICATIONS

Revise: E26.1.1(d) to read: The 27 Rivergate Drive Outfall is a 1350mm diameter Conc/1400mm diameter CMP outfall (**approx. 76.8 meter length**) that is approximately **60% - 90%** filled with sediment and debris.

DRAWINGS

Replace: 910-2022_Drawing_1-0303O-C0074-001 with 910-2022_Addendum_1-Drawing_1-0303O-C0074-001-R1

APPENDICES

Replace: 910-2022_Appendix_A with 910-2022_Addendum_1-Appendix_A