



Water and Waste Department • Service des eaux et des déchets

August 31, 2010

Our Files: 040-17-08-29-00
040-17-08-15-00
040-17-08-35-00

Ryan Coulter
Environmental Assessment and Licensing Branch
Manitoba Conservation
Suite 160 – 123 Main Street
Winnipeg, Manitoba
R3C 1A5

Dear Mr. Coulter:

RE: JULY 2010 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 R

Attached please find the July 2010 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 R issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC).

Please note the following respecting the report for Licence #2669 E RR:

1. We are pleased to report that the ammonia results have met the limit set in the licence. The total nitrogen thirty-day rolling average met the limit set in the licence in July. The total phosphorus thirty-day rolling average did not meet the limit set in the licence in July. As mentioned in previous submissions, we have experienced process issues which results in by-passing. We have also found that the total phosphorus results meet the limit set in the licence coming out of the treatment plant but the levels increase through the polishing cells.
2. There was no result for TSS on July 2 due to a technician error. The TSS values exceeded the limit set in the licence on 7 days in July. This is likely due to seasonal algae growth in the polishing cells. The TSS average result met the limit set in the licence in July.
3. There was no result for cBOD5 on July 17 due to an instrument malfunction. The cBOD5 results met the limit set in the licence in July.
4. There were no results for fecal coliform and E. coli on July 12 due to a contract lab error. We are pleased to report that during the month of July the fecal coliform and E. coli results met the limits set in the licence.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results were in excess of the 30 mg/L limit in the licence on 2 days in July. The high TSS values were due to high flows and bypass events which contributed to the increased turbidity results. The TSS average result for July met the limit set in the licence.
2. There were no results for BOD5 and cBOD5 on July 17 due to an instrument malfunction. The BOD5 results were in excess of the 30 mg/L limit in the licence on 2 days in July. The high

BOD5 values were caused by high flows due to rainfall events. The BOD5 average result for July met the limit set in the licence.

3. On July 14, the flow exceeded 380 ML/day in accordance with the licence therefore the values from that day were not included in the geometric mean calculation. On July 15, the plant flows were beyond bypass levels at the time of sampling and the values from that day were not included in the geometric mean calculation. We are pleased to report that during the month of July the fecal coliform and E. coli results met the limits set in the licence.

Please note the following respecting the report for Licence #2716 R:

1. The TSS results were in excess of the 30 mg/L limit in the licence on 2 days in July. The high TSS values were due to high flows and bypass events which contributed to the increased turbidity results. The TSS average result for July met the limit set in the licence.
2. There were no results for BOD5 and cBOD5 on July 17 due to an instrument malfunction. The BOD5 results were in excess of the 30 mg/L limit in the licence on 7 days in July. On July 8, 9, 13, and 14, the high BOD5 values were caused by high flows due to rainfall events. On July 10, 11, and 12, the high BOD5 values may have been due to a foaming and bulking issue that we have been experiencing. We have also had some shutdowns due to construction activities which may have also contributed to the high values. The BOD5 average result for July met the limit set in the licence
3. On July 9, the plant flows were beyond bypass levels at the time of sampling and the values from that day were not included in the geometric mean calculation. On July 14 and 15, the flow exceeded 98.6 ML/day in accordance with the licence therefore the values from those days were not included in the geometric mean calculation. We are pleased to report that during the month of July the fecal coliform and E. coli results met the limits set in the licence.

As mentioned in previous submissions, the City has requested that the Province change the present "daily not to exceed" BOD5 and TSS limits in the licences to monthly or running 30 day average limits. This request is under consideration by Manitoba Conservation.

The city has also requested that the Province eliminate the BOD5 test. This test is not a valid test procedure for final effluent and should not be used for compliance assessment purposes. It is important to recognize that under certain conditions, the City of Winnipeg's wastewater treatment plants experience nitrifying activity. Under such conditions the BOD5 will continue to exceed the limits from time to time. The city has requested that the BOD5 test be replaced with the carbonaceous BOD5 test.

Please let me know of any concerns or questions respecting this submission. I may be reached at the above address, by telephone at 986-4807 or by email at kkjartanson@winnipeg.ca.

Thanks for your ongoing cooperation and understanding in this matter.

Yours sincerely,

Original signed by :

K.J.T. Kjartanson, P.Eng.
Manager of Environmental Standards

KJTK/RG
Attachments

c: Cliff Lee, P.Eng., Assistant Director of Red River Region
B.D. MacBride, P.Eng. W.J. Borlase, P.Eng. M.A. Shkolny, P.Eng.