



Water and Waste Department • Service des eaux et des déchets

Environmental Standards Division • Division des Normes Environnementales

July 30, 2018

Our File No: 040-17-08-29-00
040-17-08-15-00
040-17-08-35-00
EMS

Manitoba Sustainable Development
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg, MB R3H 04W

Attention: Mr. Don Labossiere, Regional Director

**RE: JUNE 2018 MONITORING REPORTS FOR THE WEST END WATER
POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END
WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE
SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR**

The June 2018 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. There was no result for TSS on June 19 due to a technician error. The TSS results exceeded the licence limit on two days in June due to the presence of algae in the polishing pond.
2. The cBOD5 results met the licence limit in June.
3. The ammonia results and the total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in June.
4. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in June.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results exceeded the licence limit on three days in June due to intermittent high flows and bypass events.
2. The BOD5 result exceeded the licence limit on two days in June due to intermittent high flows and bypass events.
3. The monthly geometric means for fecal coliform and *E. coli* met the licence limits.

Please note the following respecting the report for Licence #2716 RR:

1. The TSS result exceeded the licence limit on one day in June due to intermittent high flows and bypass events.
2. The cBOD5 result exceeded the licence limit on one day in June due to intermittent high flows and bypass events.
3. The monthly geometric mean for *E. coli* met the licence limit in June.

Please let me know of any concerns or questions respecting this submission. I can be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Yours sincerely,

Original signed by C. Diduck for:

R. Grosselle
Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail)
C. Carroll, P. Eng (e-mail)