Safety and Health Bulletin





Asbestos Response Guide

What should I do if I suspect the work I am doing will disturb Asbestos Containing Material (ACM)?

- Follow the Safe Work Procedure for your job/task.
- ▶ If you are not sure of the Safe Work Procedure for your job/task, ask your supervisor.

What should I do if I suspect there is damaged asbestos in my area of work? (i.e., disturbed coating on wrapped pipes or boilers)

- Stop work immediately.
- Do not attempt to clean up.
- **Secure the area**. Don't let anybody in.
- ► Leave all tools and equipment on site. Lock the doors (if possible).
- ► Tell your supervisor.
- Call the plant/facility supervisor. Call the operations asbestos contact.
- Keep off the site until you are told it's safe.

Division	Plant/Facility	Facility Supervisor	Contact #	Operations Asbestos Contact	Contact #
Wastewater	NEWPCC	John Amos	986-4809 470-7326	Steve Kussy	986-4122 771-1513
	SEWPCC	Ron Hahlweg	986-5220 470-7953	Steve Kussy	986-4122 771-1513
	WEWPCC	Ron Hahlweg	986-5220 470-7953	Steve Kussy	986-4122 771-1513
	Lift/Flood Station	Dave Guse	986-4787 794-4578	Steve Kussy	986-4122 771-1513
	St. Boniface Shops	Dave Weselak	986-4120 794-4477	Steve Kussy	986-4122 771-1513
Water	552 Plinguet & Distribution System	Tammy Kauk	986-3675 471-7899	Dan Wiwchar	986-7578 479-5271
	Water Pump Station	Peter Ward	986-4785 794-4586	Dan Wiwchar	986-7578 479-5271
	Intake	Peter Ward	986-4785 794-4586	Dan Wiwchar	986-7578 479-5271

If you have a concern about disturbed asbestos after regular business hours, contact **McPhillips Control Centre at 986-4781.**