



## 908-2010 ADDENDUM 2

### 2010 OUTFALL MAINTENANCE PROGRAM: OUTFALL PIPE REPLACEMENT FOR THE CLOUTIER DRIVE OUTFALL AND THE OUTFALL REPAIRS FOR THE POLSON AVENUE AND BURROWS AVENUE OUTFALLS.

#### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE BID OPPORTUNITY**

ISSUED: December 15, 2010  
BY: Roy Houston, P.Eng.  
TELEPHONE NO. (204) 896-1209

**THIS ADDENDUM SHALL BE INCORPORATED INTO THE BID OPPORTUNITY AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS**

Template Version: A20070419

---

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid may render your Bid non-responsive.**

---

#### **PICTURES**

The Following pictures are being provided for information

Add: 908-2010\_Addendum\_2-Pictures\_Polson-R0