



BID OPPORTUNITY No. 283-2011 ADDENDUM No. 1

SUPPLY AND INSTALLATION OF BOTTOM BRACKET FAIL SAFE FALL PROTECTION DEVICES ON VARIOUS EXISTING GARAGE DOORS

URGENT

PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE BID OPPORTUNITY

ISSUED: April 8, 2011
BY: Doug Berg, C.E.T.
TELEPHONE NO. (204) 986-4452

THIS ADDENDUM SHALL BE INCORPORATED INTO THE BID OPPORTUNITY AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS

Template Version: A20070419

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.

PART E – SPECIFICATIONS

- Revise: E4.3 to read: Any adjustments or modifications required of the existing doors, door tracks, door sensors, door operators (motors), drive gear, track guards, cables, springs, rollers, wiring and other miscellaneous door hardware to allow for the proper installation of the Bottom Bracket Fail Safe Fall protection devices shall be considered incidental to the Work and no additional payment will be made for such work
- Add: E4.3.1 Some of the doors are equipped with security alarms and any adjustments and modifications, including temporary removal and reinstallation, required of any of these security alarms to return them to working condition and to allow for the proper installation of the Bottom Bracket Fail Safe Fall Protection devices shall be considered incidental to the Work and no additional payment will be made for such work.
- Add: E4.3.2 Any existing door cables that need to be replaced or renewed to allow for proper installation of the Bottom Bracket Fail Safe Fall protection devices shall be considered incidental to the Work and no additional payment will be made for such work.
- Add: E4.3.3 Any adjustments or modifications required to bring the doors into correct alignment to allow for the proper installation of the Bottom Bracket Fail Safe Fall Protection devices shall be considered incidental to the Work and no additional payment will be made for such work.