


Winter Inspections

LEGEND

- LDS
- WWS
- CB Lead
- SEWER MANHOLE
- SEWER CHAMBER
- CONTROL STRUCTURE

SITE CONSIDERATIONS:
 SITE ACCESS DIFFICULT - BLOCKED
 BY WOOD POSTS. MAY REQUIRE U/S
 ASSET FOR ACCESS.



Issue Status: Tender

Outfall Asset Number: S-MA50013076 - 17.82m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 633738.3445E, 5520283.3908N

Location: 59 BLACKMORE AVE



Drawing: 132