


Fall Inspections

LEGEND

- ▶ LDS
- ▶ WWS
- SEWER MANHOLE

SITE CONSIDERATIONS:



Issue Status: Tender

Outfall Asset Number: S-MA40000289 - 27.52m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 638412.6167E, 5535794.7272N

Location: 2065 HENDERSON HWY



Drawing: 20