

Sonar Required

LEGEND

- WWS
- SEWER MANHOLE
- SEWER CHAMBER

SITE CONSIDERATIONS:

POST AND CHAIN FENCING ACCESS FROM PARK BAY. CONTROL STRUCTURE EXISTS AT MH.

FLOW CONTROL FROM THE SEWPCC REQUIRED, NOMINAL FLOW APPROX. 20-70MEGL. FLOW REDUCTION FOR


KEY CONTACTS:

MAPLE GROVE PARK CONTACT: KARL THORDARSON: (204) 470-7821

SEWPCC CONTACT: RON HAHLEWEG: (204) 986-6159

ERIC WEISKE (SUPERVISOR OF REGIONAL WASTEWATER)
Office: (204) 986-4788
Work Cell: (204) 619-0520
Email: eweiske@winnipeg.ca
JOSE ALTOVEROS (COLLECTION)

AFFECTED RESIDENTS:



Issue Status: Tender



Drawing: 138

Outfall Asset Number: S-MA70016115 - 109.62m

Upstream Sewer Asset Number: None - 0m
Upstream Manhole Coordinates: 635411.8802E, 5517204.8867N
Location: ST MARY'S RD & PERIMETER 100 HWY