

Sonar Required

LEGEND

- LDS
- WWS
- CB Lead
- SEWER MANHOLE
- CATCH BASIN
- SEWER PUMP STATION
- CONTROL STRUCTURE

SITE CONSIDERATIONS:


ACCESS VIA BISHOP GRANDIN BV EAST BOUND. CONTROL STRUCTURE ACCESS REQUIRED.

KEY CONTACTS:

ERIC WEISKE (SUPERVISOR OF REGIONAL WASTEWATER)
Office: (204) 986-4788
Work Cell: (204) 619-0520
Email: eweiske@winnipeg.ca

JOSE ALTOVEROS (COLLECTION SYSTEM MAINTENANCE TECHNICIAN)
Office: (204) 986-7948
Email: jaltover@winnipeg.ca

AFFECTED RESIDENTS:



Issue Status: Tender



Drawing: 156

Outfall Asset Number: S-MA70087882 - 49.48m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 633472.3580E, 5520421.7817N

Location: 3100 BISHOP GRANDIN BLVD