

Appendix A

BID OPPORTUNITY 719-2016 IBM POWER SERVER REPLACEMENT

Product	Description	Qty
8286-41A	Server 1:8286 Model 41A	1
41	Device Parity Protection-All, Specify Code	1
267	IBM i Operating System Partition Specify	1
2145	Primary OS - IBM i	1
2319	Factory Deconfiguration of 1-core	3
4650	Rack Indicator- Not Factory Integrated	1
5000	Software Preload Required	1
5557	System Console-Ethernet No IOP	1
5771	SATA Slimline DVD-RAM Drive	1
5899	PCIe2 4-port 1GbE Adapter	1
5901	PCIe Dual-x4 SAS Adapter	1
6458	Power Cord 4.3m (14-ft), Drawer to Wall/IBM PDU (250V/10A)	2
9300	Language Group Specify - US English	1
9441	New IBM i License Core Counter	1
EB2M	AC Power Supply - 1400W for System Unit (200-240 VAC)	2
EB72	IBM i 7.2 Indicator	1
EJ0P	Storage Backplane 18 SFF-3 Bays/DVD Bay/Dual IOA with Write Cache	1
EJT9	Front Bezel for 18-Bay BackPlane	1
EJTN	Rack-mount Rail Kit	1
ELSU	#ESDU Load Source Specify	1
EM8B	16 GB DDR3 Memory	4
EPXK	4-Core 3.02 GHz POWER8 Processor Card	1
EPYK	One Processor Core Activation for #EPXK	4
ESC6	S&H-b	1
ESDA	283GB 15K RPM SAS SFF-3 Disk Drive (IBM i)	8
EU19	Cable Ties & Labels	1
7226-1U3	Multi-media Enclosure	1
8241	HHLT05 SAS Tape Drive	1
9400	Attached to i5 OS & OS/400 System	1
9848	Rack Device to PDU Cord	1
9849	2m Mini-SAS/Mini-SAS 1x Cable	1
5733-SPP	IBM Software Maintenance for IBM i and Selected Products, 1-Year Registration	1
A3GD	P05 0Price Per Proc 1Yr Reg	1
5770-SS1	IBM i V7	1
1448	OTC per IBM i license transfer	1
	5 year 7x24 Hardware and Software Maintenance	1