

RINK BOARD TEMPERED GLASS & SPECTATOR SAFETY NETTING REPLACEMENT- GLENWOOD COMMUNITY CENTRE -75 OVERTON STREET

URGENT

PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE BID/PROPOSAL ISSUED: February 5, 2021 BY: John Atkinson TELEPHONE NO. 204 794-4418

THIS ADDENDUM SHALL BE INCORPORATED INTO THE BID/PROPOSAL AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid/Proposal, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid/Proposal may render your Bid/Proposal non-responsive.

PART E - SPECIFICATIONS

Revise:		Removal and disposal of the existing glass, support brackets, fasteners, HDPE sill plates, HDPE sill bands, etc.to make ready for new HDPE sill plates, HDPE sill bands, supports and glass installation.
Revise:	E3.7 to read:	Supply and installation of all new 0.220 gauge orange (Arena Gold) top sill plates, sill bands, surrounding dasher boards.
Revise:	E3.10 to read	Tempered glass must have a marked identifier indicating it is tempered glass.