



## 41-2021 ADDENDUM 1

### PROFESSIONAL CONSULTING SERVICES FOR LINDEN LIFT AND FLOOD PUMPING STATION (LFPS) UPGRADES

#### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO  
WHOEVER IS IN POSSESSION OF THE  
REQUEST FOR PROPOSAL**

ISSUED: February 8th, 2021  
BY: Jurgen Friesen  
TELEPHONE NO. 204 - 986-8063

**THIS ADDENDUM SHALL BE INCORPORATED  
INTO THE REQUEST FOR PROPOSAL AND  
SHALL FORM A PART OF THE CONTRACT  
DOCUMENTS**

Template Version: Ar20180708

---

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Request for Proposal, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Proposal may render your Proposal non-responsive.**

---

#### **PART B – BIDDING PROCEDURES**

Revise: B2.1 to read: The Submission Deadline is 12:00 noon Winnipeg time, February 16<sup>th</sup>, 2021.

#### **PART D – SUPPLEMENTAL CONDITIONS**

Revise: D4.3(c)(viii) to read: Interior roof repairs – Install joist hangers and reinforce roof joists and associated works

Delete: D4.3(d)(i)

Delete: D4.3(d)(ii)

Delete: D4.3(d)(iii)

Delete: D4.3(d)(iv)

Delete: D4.3(d)(vi)

Add: D6(d)(viii) Coordinate with Manitoba Hydro to review and update if required existing facility power supply from Manitoba Hydro for new construction including renewing service conduit/overheads/transformers to the Station

Revise: D7.2(b) (ii)(c) to read: New level sensors, alarms, and transmitters or upgrades if required.

Revise: D7.2(b) (ii)(f) to read: All electrical, automation and instrumentation design must be designed to operate and integrate with existing components, i.e. Scada Systems, flood and lift pumps and motors, fans etc. in the respective LFPS.

Add: D7.2(b)( ii)(j) Temporary Power will be required during construction to maintain and keep operational lift Station pumps.

Add: D7.2(b)( iii)(k) Provide control narrative for the Contractor to program the PLC and set up communication. The Consultant will be responsible for this and will need to submit to the Department during the design process.

Delete: D7.2(c) (ii)

Revise: D7.2(d)( i)(f) to read: Interior roof repairs – Install joist hangers and reinforce roof joists

Delete: D7.2(d)( i)(g)

Delete: D7.2(d)( i)(h)

Delete: D7.2(d)( i)(i)

Delete: D7.2(d)( i)(j)