ASSET NUMBER	STREET	LOCATION DESCRIPTION	FLOW TYPE	WORK TYPE NAME	EST COST	COMMENTS	HEIGHT	WIDTH	SEWER LENGTH	START REPAIR	END REPAIR
S-MA60004428		1ST MH N OF MOUNTBATTERN AV TO 2ND MH N OF MOUNT	LDS	FULL SEGMENT LINER	\$96,300	CROSSBORE PIPE	750	750	96.4	0.0	96.3
S-MA40006736	BRAZIER ST	MH AT GREENE AV TO MH AT LINDEN AV	CS	FULL SEGMENT LINER	\$117,500		900	900	80.1	0.0	79.5
S-MA20011968	CECIL ST()	MH AT ROY AV.TO MH AT PACIFIC AV.W.	CS	FULL SEGMENT LINER	\$44,100		750	750	38.0	0.0	38.0
S-MA20016628	COLONY ST	MH @ BALMORAL ST TO 1ST MH N OF PORTAGE AV	CS	FULL SEGMENT LINER	\$157,500	MB, IMAGES AVAIL.	800	1200	137.8	0.0	134.4
S-MA40012891	DAY ST	1ST MH S OF THOM AV TO 1ST MH S OF MCMEANS AV	LDS	FULL SEGMENT LINER	\$179,000		750	750	169.7	0.0	169.7
S-MA50004057	GAUVIN ST	1ST MH S OF CONISTON ST TO 2ND MH S OF CONISTON ST	CS	FULL SEGMENT LINER	\$50,200	FL THROUGHOUT - H @ INVERFACE W/ MH 8667 - IMAGES AVAILABLE	600	600	61.0	0.0	60.7
S-MA50007514	HILL ST.	MH AT NIVERVILLE ST TO 1ST MH S OF NIVERVILLE ST	CS	AUGMENTED FS LINER	\$46,000	epr 75.3-79m	600	600	93.5	0.0	92.4
S-MA50015297	LANE N OF ST MICHAEL RD	3RD MH N OF PULBERRY ST TO MH AT ST MARYS RD	LDS	TRENCHLESS PT REPAIR		B, FM TRENCHLEES POINT REPAIR ONLY REQUIRED HOWEVER MAY BE TO ADDRESSED WITH FSL IF TPR CAN'T BE DONE PWD STREET RENEWAL IN 2021	600	600	51.7	0.2	3.0
S-MA20009893	SARGENT AV CL	MH AT DUNDAS ST TO TE AT MILT STEGAL DR	CS	FULL SEGMENT LINER	\$105,800	PWD STREET RENEWAL IN 2021	750	750	87.7	0.0	87.7
\$810,400											