

65mm Caliper, 3500-4000mm Ht., min. 700mmØ rootball, Straight sturdy trunks, well-branched and balanced, min. 10 major branches 2000mm above grade, B & B or tree mover, wire basket. 65mm Caliper, 3500-4000mm Ht., min. 700mmØ rootball. Straight sturdy trunks, well-branched and balanced head, min. 10 major branches 2000mm above grade. B & B or tree mover, wire basket. 50mm Caliper, 2400-3000mm Ht., min. 600mmØ rootball. Well-branched and balanced, min. 10 major branches. B & B or tree mover, wire basket.	500mm or As Shown As Shown 5,000mm D.C. or As Shown
Straight sturdy trunks, well-branched and balanced, min. 10 7 major branches 2000mm above grade, B & B or tree mover, 8 65mm Caliper, 3500-4000mm Ht., min. 700mmØ rootball. 5 Straight sturdy trunks, well-branched and balanced head, 7 min. 10 major branches 2000mm above grade. 8 B & B or tree mover, wire basket. 50 50mm Caliper, 2400-3000mm Ht., min. 600mmØ rootball. 5 Well-branched and balanced, min. 10 major branches. B & B or tree mover, wire basket. 5 Well-branched and balanced, min. 10 major branches. B & B or tree mover, wire basket. 5 Well-branched and balanced, min. 10 major branches. B & B or tree mover, wire basket. 5 2400mm Ht., 900mm base width,min. 900mm wide rootball. 5 Single upright (no broken) leader, well-branched, 1 full form 360° to grade. Machine dug. Root flare to be 1	or As Shown As Shown 5,000mm D.C. or As
Straight sturdy trunks, well-branched and balanced head, min. 10 major branches 2000mm above grade. A B & B or tree mover, wire basket. 50mm Caliper, 2400-3000mm Ht., min. 600mmØ rootball. 50mm Caliper, 2400-3000mm Ht., min. 600mmØ rootball. 50mm Pressent and balanced, min. 10 major branches. B & B or tree mover, wire basket. 2400mm Ht., 900mm base width, min. 900mm wide rootball. 50mm Single upright (no broken) leader, well-branched, full form 360° to grade. Machine dug. Root flare to be	6,000mm D.C. or As
Well-branched and balanced, min. 10 major branches. B & C B or tree mover, wire basket. 2400mm Ht., 900mm base width,min. 900mm wide rootball. Single upright (no broken) leader, well-branched, full form 360° to grade. Machine dug. Root flare to be	D.C. or As
Single upright (no broken) leader, well-branched, full form 360° to grade. Machine dug. Root flare to be	
	2'-0"
Evenly branched, full bushy trees, no broken leaders, well branched to grade B & B or tree mover, wire basket. Guy A wire	As Shown
400 mm Height. MIN. 4 major basal branches. Well formed, bushy plants, even form	As Shown
#1 Container. 2 year old plants. Well developed root system	s Shown
#1 Container. Well developed root system. Min. 3 runners	As Shown
THE CITY OF WINNIP WATER AND WASTE DEPARTM SOLID WASTE DIVISION	
	EET 2 OF 5
PLANTING PROJECT	Y DRAWING NUMBER
TRATION BUILDING ANTING PLAN	0400C-B0001-0