



Water and Waste Department • Service des eaux et des déchets

---

June 27, 2014

Our Files: 040-17-08-29-00  
040-17-08-15-00  
040-17-08-35-00

Don Labossiere  
Director, Environmental Compliance and Enforcement  
Manitoba Conservation and Water Stewardship  
123 Main Street  
Winnipeg MB R3C 1A5

Dear Mr. Labossiere:

**RE: MAY 2014 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR**

Attached please find the May 2014 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC). This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. We are pleased to report that the ammonia results have met the limit set in the licence. The total nitrogen and total phosphorus thirty-day rolling averages met the limits set in the licence in May.
2. The TSS results met the limit set in the licence in May.
3. The cBOD5 results met the limit set in the licence in May.
4. We are pleased to report that during the month of May the fecal coliform and E. coli results met the limits set in the licence.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results exceeded the licence limit on 3 days in May. The high TSS values were due to intermittent high flows and bypass events which contributed to the increased TSS results.
2. There were no BOD5 and cBOD5 results on May 11 due to a sample preparation error. The BOD5 results exceeded the licence limit on 4 days in May. The high BOD5 values were due to intermittent high flows and bypass events.

3. We are pleased to report that during the month of May the fecal coliform and E. coli results met the limits set in the licence.

Please note the following respecting the report for Licence #2716 RR:

1. On May 15, there was no final effluent 24 hour composite sample due to a sampler malfunction.
2. The TSS results met the limit set in the licence in May.
3. The cBOD5 results met the limit set in the licence in May.
4. We are pleased to report that during the month of May the E. coli result met the limit set in the licence.

Please let me know of any concerns or questions respecting this submission. I may be reached by telephone at 204-986-4807 or by email at [kkjartanson@winnipeg.ca](mailto:kkjartanson@winnipeg.ca).

Thanks for your ongoing cooperation and understanding in this matter.

Yours sincerely,

*Original signed by:*

K.J.T. Kjartanson, P.Eng.  
Manager of Environmental Standards

KJTK/rg  
Attachments

c: D. P. Sacher, P.Eng. (e-mail)  
C. Carroll, P.Eng. (e-mail)

N:\Compliance Reporting\WPCC Monthly\2014 Submitted Letters\Submittal Letter WPCC Monitoring May 2014.doc