



Water and Waste Department • Service des eaux et des déchets

January 29, 2016

Our Files: 040-17-08-29-00
040-17-08-15-00
040-17-08-35-00

Don Labossiere, Regional Director
Manitoba Conservation and Water Stewardship
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg MB R3H 0W4

Dear Mr. Labossiere:

RE: DECEMBER 2015 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR

The December 2015 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. There were no results for fecal coliform and *E. coli* on December 3 and 4 due to a contract lab error.
2. All results reported for Licence #2669 E RR RR met the licence requirements in December.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results exceeded the licence limit on 3 days in December. The cause of the exceedances on December 8 and 22 is unknown. On December 29, we experienced a short-term process issue which may have been caused by an unknown substance that went through the system resulting in a high TSS result.
2. There was no result for cBOD5 on December 1 due to a technician error. The BOD5 results met the licence limit in December.
3. There were no results for fecal coliform and *E. coli* on December 3 and 4 due to a contract lab error. The monthly geometric mean for fecal coliform and *E. coli* met the licence limits in December.

Please note the following respecting the report for Licence #2716 RR:

1. There was no result for *E. coli* on December 3 and 4 due to contract lab error.
2. There was no result for cBOD5 on December 1 due to a technician error.

3. All results reported for Licence #2716 RR met the licence requirements in December.

Please let me know of any concerns or questions respecting this submission. I may be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Thank you for your ongoing cooperation and understanding in this matter.

Yours sincerely,

Original signed by:

R. Grosselle
Manager of Environmental Standards

RG
Attachments

c: D. P. Sacher, P.Eng. (e-mail)
C. Carroll, P.Eng. (e-mail)

N:\Compliance Reporting\WPCO Monthly\2015 Submittal Letters WPCO\2015-12 Submittal Letter WPCO Monitoring.docx