



Water and Waste Department • Service des eaux et des déchets

January 30, 2017

Our File No: 040-17-08-29-00
040-17-08-15-00
040-17-08-35-00

Manitoba Sustainable Development
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg, MB R3H 04W

Attention: Mr. Don Labossiere, Regional Director

RE: DECEMBER 2016 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR

The December 2016 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. There were no 24-hour composite samples on December 8, 9, and 10 due to sampler malfunctions and no sample on December 14 due to a fridge malfunction. There was no 24-hour composite sample on December 26 because the sampling location was inaccessible due to snow, and the December 27 sample was not representative due to a sample overflow.
2. The TSS results met the licence limit in December.
3. There was no result for cBOD5 on December 15 due to a QC failure; the cBOD5 results met the licence limit in December.
4. The ammonia results met the licence limit in December.
5. The total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in December.
6. There were no grab samples on December 6 and 27 because the sampling location was inaccessible due to snow. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in December.



Environmental Standards Division • Division des normes environnementales
2230 Main Street • 2230, Rue Main • Winnipeg • Manitoba R2V 4T8
tel/tél. (204) 986-4684 • fax/télec. (204) 339-2147 • www.winnipeg.ca

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results met the licence limit in December.
2. There were no results for BOD5 and cBOD5 on December 14 and 15 due to QC failures. The BOD5 results met the licence limit in December.
3. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in December.

Please note the following respecting the report for Licence #2716 RR:

1. The TSS results met the licence limit in December.
2. There were no results for BOD5 or cBOD5 on December 14 and 15 due to QC failures. The cBOD5 results met the licence limit in December.
3. There was no grab sample on December 6 because the sampling location was inaccessible due to snow. The monthly geometric mean for *E. coli* met the licence limit in December.

Please let me know of any concerns or questions respecting this submission. I may be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Yours sincerely,

Original signed by:

R. Grosselle
Manager of Environmental Standards

NC
Attachments

c: M. L. Geer CPA, CA (e-mail)
C. Carroll, P. Eng (e-mail)

N:\Compliance Reporting\WPCC Monthly\2016 Submitted Letters WPCC\2016-12 Submittal Letter WPCC Monitoring.docx