



Water and Waste Department • Service des eaux et des déchets

Environmental Standards Division • Division des Normes Environnementales

January 30, 2018

Our File No: 040-17-08-29-00
040-17-08-15-00
040-17-08-35-00
EMS

Manitoba Sustainable Development
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg, MB R3H 04W

Attention: Mr. Don Labossiere, Regional Director

**RE: DECEMBER 2017 MONITORING REPORTS FOR THE WEST END WATER
POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END
WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE
SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR**

The December 2017 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. The TSS results met the licence limit in December.
2. There were no results for cBOD5 on December 8, 11, and 18 due to QC failures; the cBOD5 results met the licence limit in December.
3. The ammonia results and the total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in December.
4. There was no result for temperature for the grab sample on December 7 due to a technician error, and no sample for pH on December 15 due to a sample leak.
5. There were no results for *E. coli* on December 20 and fecal coliform on December 30 due to contract lab errors; the monthly geometric means for fecal coliform and *E. coli* met the licence limits in December.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS results met the licence limit in December.
2. There were no results for BOD5 and cBOD5 on December 8, 11, and 18 due to QC failures; the BOD5 results met the licence limits in December.
3. There were no results for *E. coli* on December 19 and fecal coliform on December 29 due to contract lab errors; the monthly geometric means for fecal coliform and *E. coli* met the licence limits in December.

Please note the following respecting the report for Licence #2716 RR:

1. The TSS results met the licence limit in December.
2. There were no results for BOD5 and cBOD5 on December 8, 11, and 18 due to QC failures; the cBOD5 results met the licence limits in December.
3. There was no result for temperature for the grab sample on December 7 and no result for pH on December 10 due to technician errors.
4. There was no result for E.coli on December 20 due to a contract lab error; the monthly geometric mean for *E. coli* met the licence limit in December.

Please let me know of any concerns or questions respecting this submission. I can be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Yours sincerely,

Original signed by R. Grosselle:

R. Grosselle
Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail)
C. Carroll, P. Eng (e-mail)