



Water and Waste Department • Service des eaux et des déchets

Environmental Standards Division • Division des Normes Environnementales

October 30, 2017

Our File No: 040-17-08-29-00

Manitoba Sustainable Development
Environmental Compliance and Enforcement Branch
1007 Century Street
Winnipeg, MB R3H 04W

040-17-08-15-00

040-17-08-35-00

EMS

Attention: Mr. Don Labossiere, Regional Director

RE: SEPTEMBER 2017 MONITORING REPORTS FOR THE WEST END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2669 E RR, THE NORTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2684 RRR AND THE SOUTH END WATER POLLUTION CONTROL CENTRE LICENCE NO. 2716 RR

The September 2017 Monitoring Reports for Licence No. 2669 E RR issued for the City of Winnipeg West End Water Pollution Control Centre (WEWPCC), Licence No. 2684 RRR issued for the City of Winnipeg North End Water Pollution Control Centre (NEWPCC) and Licence No. 2716 RR issued for the City of Winnipeg South End Water Pollution Control Centre (SEWPCC) are attached. This information is provided under compulsion of law in accordance with the requirements under the Environment Act Licences #2669 E RR, #2684 RRR and #2716 RR.

Please note the following respecting the report for Licence #2669 E RR:

1. The TSS results met the licence limit in September.
2. There the cBOD5 results met the licence limit in September.
3. The ammonia results met the licence limit in September.
4. The total phosphorus and total nitrogen thirty-day rolling averages met the licence limits in September.
5. There was no final effluent grab sample on September 19 due to maintenance activities and a technician error. The monthly geometric means for fecal coliform and *E. coli* exceeded the licence limits in September due to the high geese population in the polishing cells.

Please note the following respecting the report for Licence #2684 RRR:

1. The TSS result exceeded the licence limit from September 8 to 13 as a result of scheduled maintenance activities.
2. The TSS and BOD5 results exceeded the licence limits on three days in September due to intermittent high flows and by-pass events.
3. The monthly geometric means for fecal coliform and *E. coli* met the licence limits in September.

Please note the following respecting the report for Licence #2716 RR:

1. The TSS and cBOD5 results exceeded the licence limits on one day in September due to intermittent high flows and by-pass events.
2. The monthly geometric mean for *E. coli* met the licence limit in September.

Please let me know of any concerns or questions respecting this submission. I can be reached by telephone at 204-986-8359 or by email at rgrosselle@winnipeg.ca.

Yours sincerely,

Original signed by R. Grosselle:

R. Grosselle
Manager of Environmental Standards

NC

Enclosures

cc: M. L. Geer CPA, CA (e-mail)
C. Carroll, P. Eng (e-mail)