

Existing Conditions Photos

Bid Opportunity No:

443-2013

Name of Project:

Sir John Franklin CC Basement Structural Repairs

Project Location:

Sir John Franklin Satellite Site (CC-079)

1 Sir John Franklin Road, Winnipeg, Manitoba



IMG_2482



IMG_2483



IMG_2484



IMG_2485



IMG_2486



IMG_2487



IMG_2488



IMG_2489



IMG_2490



IMG_2491




IMG_2492



IMG_2493



IMG_2494



IMG_2495



IMG_2496



IMG_2497




IMG_2498



IMG_2499



IMG_2500



IMG_2501



IMG_2502



IMG_2503



IMG_2504



IMG_2505



IMG_2506



IMG_2507



IMG_2508



IMG_2509



IMG_2510



IMG_2511



IMG_2512



IMG_2513



IMG_2514



IMG_2515



IMG_2516



IMG_2517



IMG_2518



IMG_2519




IMG_2520



IMG_2521



IMG_2522




IMG_2523



IMG_2524




IMG_2525




IMG_2526



IMG_2527




IMG_2528



IMG_2529



IMG_2530



IMG_2531