

**APPENDIX B(R1) - TABLE E7.2 : SITE SPECIFIC MANHOLE CONDITIONS AND REPAIR REQUIREMENTS**

	STREET_NAME	LOCATION_DETAILS	MANHOLE_ID	REPAIRS_REQUIRED
1	Brewster Bay (E Leg)	MH at NPL Kildare Ave W	S-MH40012088	Grout cracked riser ring
2	Brewster Street	MH at Cloverdale Cres	S-MH40012023	<b>Grout under MH frame</b>
3	Camelot Court	1st MH W of Redonda St	S-MH40008939	<b>Grout under MH frame</b>
4	Camelot Court	2nd MH W of Redonda St	S-MH40008896	<b>Grout under MH frame</b>
5	Crossgate Road	MH at Whitehall Blvd	S-MH40008864	<b>Grout under MH frame</b>
6	Day Street	MH at Whittier Ave	S-MH40012564	Replace 0.3m riser below frame with flat top reducer, grout around E pipe connection
7	Gables Court	MH at Kildare Ave E	S-MH40009035	<b>Grout under MH frame</b>
8	Hoka Street	MH at Rosseau Avenue W	S-MH40012034	Install 2 MH rungs
9	Horton Avenue W	MH at Winona St	S-MH40012423	Replace 1.0m riser below frame
10	Kernaghan Avenue	5th MH W of Hoka St	S-MH40010760	<b>Grout under MH frame</b>
11	Kernaghan Avenue	6th MH W of Hoka St	S-MH40011109	Grout 0.5m riser below frame
12	Knightsbridge Drive	1st MH N of Meadowood Dr	S-MH50012598	<b>Grout under MH frame</b>
13	Larson Avenue	MH at Henderson Hwy	S-MH40004801	<b>Grout cracked riser ring</b>
14	Lethbridge Avenue	MH at Kootenay Ave	S-MH40011837	<b>Grout under MH frame</b>
15	Lethbridge Avenue	1st MH E of Kootenay Ave	S-MH40011853	Install benching in Manhole, replace cracked MH lid
16	McMeans Ave E (SPL)	MH at Alex Taylor Dr	S-MH40008470	Replace broken 75mm riser ring under frame
17	Neil Avenue	3rd MH W of Watt St	S-MH40004566	Grout cracked riser ring
18	Pandora Avenue E	2nd MH E of Wayoata St	S-MH40008218	<b>Grout under MH frame</b> , replace cracked lid
19	Park Circle	MH at Wabasha St	S-MH70050151	Grout around SE pipe connection
20	Park Circle	1st MH N of Ravelston Ave E	S-MH40012535	Install benching in Manhole
21	Redonda Street	1st MH S of Kildare Ave E	S-MH40008900	Grout cracked riser under frame
22	Redonda Street	2nd MH S of Kildare Ave E	S-MH40008901	Replace Cracked Lid
23	Redonda Street	1st MH N of Victoria Ave E	S-MH40008951	Replace broken frame
24	Redonda Street	2nd MH N of Victoria Ave E	S-MH40008952	Install 1 MH rung
25	Redonda Street	MH at Pandora Ave E	S-MH40008182	Replace broken 75mm riser ring under frame
26	Regent Avenue W	1st MH E of Winona St	S-MH40010676	Install benching in Manhole
27	Regent Avenue W	MH at Winona St	S-MH40010646	Replace 0.75m bricks under frame with concrete riser
28	Victoria Ave E	MH at Brelade St	S-MH40008911	Replace broken 150mm riser ring under frame
29	Vista Avenue	MH N.E. Cul De Sac	S-MH50011145	Grout cracked 75mm riser ring
30	Wabasha Street	MH at Melrose Ave E	S-MH40010730	Grout riser ring below frame
31	Wabasha Street (Easement Kern Park)	MH at Kern Drive	S-MH40012607	Grout 0.6m riser below frame
32	Wayoata Street	1st MH N of Coldstream Ave	S-MH40008757	<b>Grout under MH frame</b>
33	Wayoata Street	Mh at Harvard Ave E	S-MH40008759	<b>Grout under MH frame</b>