# **APPENDIX 'C'**

# **GEOTECHNICAL REPORT**

3

## APPENDIX 'C' - GEOTECHNICAL REPORT

#### TABLE OF CONTENTS


GEOTECHNICAL REPORT FOR MAIN STREET FROM MCADAM AVE TO KILDONAN PARK GOLF COURSE	1
Pavement Core Locations	1
Summary of Core Samples	1

Summary of Core Samples Pavement Core Photos

The geotechnical report is provided to aid in the Contractor's evaluation of the existing pavement structure. The information presented is considered accurate at the locations shown on the Drawings and at the time of coring. However, variations in pavement structure may exist between test holes. The nature and extent of variations may not become evident until construction commences.

#### Geotechnical Report for Main Street from McAdam Ave to Kildonan Park Golf Course

### **Pavement Core Locations**



# **Summary of Core Samples**

Core ID	Testhole Location	Pavement Surface		
Core ID		Туре	Thickness (mm)	Comments
C01	Main Street Northbound middle lane, 31 m north of Rupertsland Avenue 6 m west of east curb	Asphalt	0	<ul> <li>core located on joint of concrete slabs.</li> </ul>
		Concrete	200	<ul> <li>crushed limestone base below concrete pavement</li> </ul>
C02	Main Street Southbound median lane, At Jefferson Avenue intersection 0 m of east curb	Asphalt	0 135*	<ul> <li>core located on asphalt/concrete joint of south Main Street and Jefferson Avenue at median boulevard</li> </ul>
		Concrete	265 130*	(asphalt on southbound Main Street) • crushed limestone base below concrete pavement
C03	Main Street Northbound median lane, 36m north of Hardford Avenue 9 m west of east curb	Asphalt	0	<ul> <li>core located on joint of concrete slabs.</li> <li>crushed limestone base below concrete pavement</li> </ul>
		Concrete	190	
C04	Main Street Northbound curb lane, 27 m south of Burrin Avenue 2 m west of east curb	Asphalt	0	<ul> <li>core located on middle of concrete slab.</li> </ul>
C04		Concrete	200	<ul> <li>crushed limestone base below concrete pavement</li> </ul>
C05	Main Street Southbound median lane, At Royal Avenue intersection 0 m of east curb	Asphalt	0 50*	<ul> <li>core located on asphalt/concrete joint of south Main Street and Royal Avenue at median boulevard (asphalt</li> </ul>
		Concrete	260 210*	on southbound Main Street) • crushed limestone base below concrete pavement
C06	Main Street Northbound median lane, 30 m south of Armstrong Avenue 9 m west of east curb	Asphalt	0	<ul> <li>core located on middle of concrete slab.</li> </ul>
		Concrete	205	<ul> <li>crushed limestone base below concrete pavement</li> </ul>

Notes: 1. \* denotes the half of the core sample with asphalt and concrete pavement. Core sample is located on a joint with one half asphalt and concrete pavement and the other half concrete pavement.

# **Pavement Core Photos**



Figure 1 - C01 Core



Figure 2 - C02 Core






Figure 3 - C03 Core

Figure 4 - C04 Core





Figure 5 - C05 Core



Figure 6 - C06 Core