








**THE CITY OF WINNIPEG
WATER AND WASTE DEPARTMENT**

**Request for Proposal No. 61-2020
2019 BRANCH I AQUEDUCT UNDERDRAIN
CONDITION ASSESSMENT**

IDENTIFIERS AND SIZES

Legend

- | | | | |
|---|--|---|----------------|
|  | AQUEDUCT UNDERDRAIN
(to be cleaned and inspected) |  | SEWER MAIN |
|  | AQUEDUCT |  | WWS SEWER MAIN |
|  | UNDERDRAIN MANHOLE
(to be cleaned and inspected) |  | LDS SEWER MAIN |
| | |  | SEWER MANHOLE |

**ASSOCIATED
AS-BUILT RECORDS**

- D-6344
- D-6345
- D-6346
- D-6347
- D-6348

MAP 13



REVISION 0
15/01/2020

